Work Report Summary

Date Range: 8 April-13 April 2019

Name: Simran Malhotra Subsystem: Coding

Issue#1 Progress

• Installed ROS and I have gone through a few topics in the Documentation.

WRO 2019 Progress

• **Encoder Motor**-Worked with Encoder Motor(RMCS-2284) and wrote a code to test its functionality but there were some issues.

https://github.com/RoboManipal-9-0/Coding-FirstYears/blob/Simran/Encoder.ino

Getting Encoder Values from different motors using Multiplexer-Understood the
working of a multiplexer and wrote a code to get encoder values from four different
motors connected to the input pins on the multiplexer. Testing needs to be done.

https://github.com/RoboManipal-9-0/Coding-FirstYears/blob/Simran/Multiplexer.ino

 PID(Proportional-Integral-Derivative) Controller-Understood the working principle of a PID Controller and went through the PID Library on GitHub.

Current Issues

Issue#1

Issues Faced:

 Was unable to install ROS initially on my Mac but the issue was resolved. I installed Ubuntu on Virtual box.

Encoder Motor

Issues Faced:

 The code was working but the encoder value was getting reseted to zero after a specified rotation.