



3.90 s




(a) T01 Parallel sorting

9.60 s




(b) T02 Shared inspection

5.70 s




(c) T03 Synchronized kitting

25.60 s




(d) T04 Two-stage shared service

9.00 s




(e) T05 Cooperative transfer

21.00 s




(f) T06 Two-leg transfer

21.00 s



(g) T07 Loading and transfer

21.20 s



(h) T08 Transfer and unloading