Main Battery voltage for motors. Te buck converter provides the 5v power supply for the PI board and the modules.

RJ Connectors, signal level shifters for I2C protection, utility buttons and power-indicative LEDs

