

1 Arrival

Visitors to the fixture workshop sign the arrival sheet at the front desk.

Badges are collected from the desk clerk before entering the workshop floor.

2 Equipment

Every bench instrument requires calibration before first use each day.

The calibration result is written on the bench card, and instruments that fail the check are tagged and moved to the repair

shelf until the technician returns them to service.

3 Departure

Visitors return their badges to the desk clerk when they leave the workshop.