

SYMBOLS AND LEGEND



Contact, NO



Contact, NC



Coil



Indicator lamp



Motor



Fuse



Isolator



E-stop

DEVICE TAGS

- Q
- Circuit breaker, isolator
- F
- Fuse, protective device
- K
- Relay
- KM
- Contactor
- M
- Motor
- S
- Switch, pushbutton
- B
- Sensor, transducer
- H
- Indicator, beacon
- T
- Transformer, power supply
- A
- Assembly; PLC, drive, safety relay
- X
- Terminal
- W
- Cable

PROJECT	IntegraCAD Open		
TITLE	Symbols and legend		
CLIENT	DRAWN		
DRAWING No.	REV	SCALE	DATE
003	0	1:1	2026-10-06