


CSigUnit_Debug.h File Reference


```
#include <sys/slog2.h>
```

```
#include <stdint.h>
```

Include dependency graph for CSigUnit_Debug.h:



This graph shows which files directly or indirectly include this file:



[Go to the source code of this file.](#)

Macros

```
#define LOG_FMT "%s:%d "
```

```
#define LOG_ARGS __func__, __LINE__
```

```
#define NEWLINE " "
```

```
#define LOG_ERROR(msg, vars...) (void)slog2f(slog_handle, 0, SLOG2_ERROR, LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

```
#define LOG_WARNING(msg, vars...) (void)slog2f(slog_handle, 0, SLOG2_WARNING, LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

```
#define LOG_INFO(msg, vars...) (void)slog2f(slog_handle, 0, SLOG2_INFO, LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

```
#define LOG_DEBUG(msg, vars...) (void)slog2f(slog_handle, 0, SLOG2_DEBUG1, LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

Functions

```
uint8_t sigunit_enable_logging (void)
```

Function that is called to register with slogger2 so that slog2info logs are logged. [More...](#)

Variables

```
slog2_buffer_set_config_t slog_config
```

Macro Definition Documentation

◆ LOG_ARGS

```
#define LOG_ARGS __func__, __LINE__
```

◆ LOG_DEBUG

```
#define LOG_DEBUG ( msg,  
                    vars...  
                ) (void)slog2f(slog_handle, 0, SLOG2_DEBUG1,LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

◆ LOG_ERROR

```
#define LOG_ERROR ( msg,  
                    vars...  
                ) (void)slog2f(slog_handle, 0, SLOG2_ERROR,LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

◆ LOG_FMT

```
#define LOG_FMT "%s:%d "
```

◆ LOG_INFO

```
#define LOG_INFO ( msg,  
                   vars...  
                ) (void)slog2f(slog_handle, 0, SLOG2_INFO,LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

◆ LOG_WARNING

```
#define LOG_WARNING ( msg,  
                      vars...  
                    ) (void)slog2f(slog_handle, 0, SLOG2_WARNING,LOG_FMT msg NEWLINE, LOG_ARGS, ##vars)
```

◆ NEWLINE

```
#define NEWLINE " "
```

Function Documentation

◆ sigunit_enable_logging()

uint8_t sigunit_enable_logging (void)

Function that is called to register with slogger2 so that slog2info logs are logged.

Function Name: sigunit_enable_logging


Parameters

void


Returns

uint8_t

Here is the call graph for this function:



Here is the caller graph for this function:



Variable Documentation

◆ slog_config

slog2_buffer_set_config_t slog_config

◆ slog_handle

slog2_buffer_t slog_handle