


wd.h File Reference

This graph shows which files directly or indirectly include this file:



Go to the source code of this file.

Macros

#define **RTI_WDT_TIMEOUT** (1000U)

Functions

void **InternalWatchdog_Enable** (void)
Enable the watchdog, call after system init. [More...](#)

void **InternalWatchdog_PrintResetStatus** (void)
Prints status of RTI Watchdog, taken while enabling WD. [More...](#)

void **InternalWatchdog_Test** (void)

void **InternalWatchdog_Service** (void)
Service (pet) the watchdog. [More...](#)

void **InternalWatchdog_DoReset** (void)
Cause the watchdog to reset the system. [More...](#)

Macro Definition Documentation

◆ RTI_WDT_TIMEOUT

```
#define RTI_WDT_TIMEOUT (1000U)
```

Function Documentation

◆ InternalWatchdog_DoReset()

InternalWatchdog_DoReset (void)

Cause the watchdog to reset the system.

Returns

void

◆ InternalWatchdog_Enable()


InternalWatchdog_Enable (void)

Enable the watchdog, call after system init.

Returns

void

Here is the call graph for this function:



◆ InternalWatchdog_PrintResetStatus()

InternalWatchdog_PrintResetStatus (void)

Prints status of RTI Watchdog, taken while enabling WD.

Returns

void

◆ InternalWatchdog_Service()

InternalWatchdog_Service (void)

Service (pet) the watchdog.

Returns

void

◆ InternalWatchdog_Test()

void InternalWatchdog_Test (void)