Consor
Sensor
+ Sensor()
+ ~Sensor()
+ readSensorVal()
Д
Humidity
+ Humidity()
+ ~Humidity()
+ readHumidity()