Lift inspection report

Lift ID: LFT-34830

Location: 8 Beacon Hill, Ashdale

Inspection date: 2026-10-01

Technician: Diego Navas

No.	Location	Defect description	Qty
1	floor 2	LDG DR RLR LSE	3
2	machine room	Gearbox oil change required	1
3	pit	Travelling cable, 24-core out of adjustment	60 m
4	machine room	MOTOR ENCODER INCREMENTAL CORR	1
5	floor 0	Door operator belt worn	1
6	machine room	Hydraulic hose, 1 m broken	1
7	machine room	Brake coil loose	2
8	car top	SLACK ROPE SW CORR	1
9	car top	Overspeed governor, service and test required	1
10	pit	Buffer, counterweight, spring faulty	2
11	floor 6	HALL LANTERN DMGD	1
12	car top	Safety gear adjustment required	1
13	pit	RAIL LUBR CWT WRN	3
14	machine room	Inverter cooling fan corroded	2

No.	Location	Defect description	Qty
15	machine room	Load weighing sensor corroded	1
16	pit	BUFFER CWT SPRING DMGD	2
17	floor 0	DR SILL ADJ AND CLEANING REQUIRED	2
18	pit	PIT STOP SW OUT OF ADJ	2