Lift inspection report

Lift ID: LFT-73974

Location: 91 Orchard Way, Fairholm

Inspection date: 2026-09-30

Technician: Jorge Ferrer

No.	Location	Defect description	Qty
1	machine room	Control cabinet fan corroded	1
2	machine room	Machine room lighting fitting out of adjustment	2
3	machine room	Gearbox oil change required	1
4	machine room	MOTOR ENCODER OUT OF ADJ	1
5	car top	Overspeed governor, replacement required	1
6	floor 4	HALL LANTERN OUT OF ADJ	3
7	machine room	RESIDUAL CURRENT DEVICE NOT WKG	1
8	car top	Final limit switch, upper faulty	1
9	floor 4	Door sill adjustment and cleaning, landing required	2
10	floor 6	Landing door interlock worn	4
11	car	CAR VENT FAN FLTY	1
12	car	Car apron damaged	1