Periodic inspection findings

Lift no. LFT-98744

Address 79 Larch Street, Westmere

Date 02/09/2026

Inspector Diego Vidal

Ref	Finding
F-01	floor 9: CAR DR CONT FLTY (qty 1)
F-02	machine room: M/C ROOM SOCKET DMGD (qty 1)
F-03	floor 0: Landing door roller, 60 mm out of adjustment (qty 1)
F-04	building: Graffiti on the car walls (qty 1)
F-05	floor 0: OVERLOAD IND DMGD (qty 1)
F-06	machine room: PHASE MONITORING RELAY LSE (qty 1)
F-07	floor 7: Braille floor plate loose (qty 2)
F-08	floor 9: Landing door roller, 80 mm out of adjustment (qty 1)
F-09	floor 1: Landing door interlock, electrical contact corroded (qty 3)
F-10	machine room: TRACTION SHEAVE BRKN (qty 1)
F-11	machine room: RESIDUAL CURRENT DEVICE OUT OF ADJ (qty 1)
F-12	pit: Counterweight guide shoe insert, sliding not working (qty 4)
F-13	car: Car apron broken (qty 1)