Lift inspection report

Lift ID: LFT-44549

Location: 81 Harbour Avenue, Eastbrook

Inspection date: 2026-10-20

Technician: Pablo Rubio

No.	Location	Defect description	Qty
1	pit	Rope fastening, wedge socket out of adjustment	4
2	floor 4	Landing key switch loose	3
3	machine room	Motor encoder, incremental worn	1
4	car	Car mirror corroded	1
5	floor 9	Door sill adjustment and cleaning, landing required	1
6	car top	Unintended car movement detector out of adjustment	1
7	machine room	Load weighing sensor loose	1
8	building	Pigeons nesting on the machine room roof	1
9	machine room	MOTOR BRG NON-DRIVE END NOT WKG	2
10	floor 6	Landing door closer, spring loose	4
11	machine room	Door zone switch worn	1