Lift inspection report

Lift ID: LFT-23270

Location: 18 Chapel Row, Northgate

Inspection date: 2026-10-03

Technician: Irene Rubio

No.	Location	Defect description	Qty
1	car top	Safety gear adjustment required	1
2	car top	Alarm battery worn	1
3	car	Car floor covering, rubber faulty	4 m2
4	floor 9	Landing door closer, weight and cable out of adjustment	4
5	floor 2	Voice announcer damaged	1
6	pit	Counterweight filler weight not working	4
7	floor 7	Landing key switch not working	1
8	car top	Emergency light battery out of adjustment	2
9	building	Pigeons nesting on the machine room roof	1
10	floor 3	Braille floor plate worn	3
11	car top	Alarm battery damaged	2
12	pit	Governor tension pulley faulty	1
13	machine room	Phase monitoring relay corroded	1
14	car	CAR HANDRAIL ALUMINIUM BRKN	3

No.	Location	Defect description	Qty
15	floor 0	HALL POS IND TFT COLOUR LSE	3
16	car	Car handrail, stainless steel damaged	3
17	car top	Emergency telephone, landline unit damaged	1
18	machine room	Main contactor damaged	3