Branch maintenance form

Unit no.	LFT-54199	**Date of visit**	08 Sep 2026
Site address	25 Larch Street, Eastbrook	**Engineer**	Marta Ferrer

Pos.	Component	Observation	Units
1	Machine room lighting fitting	corroded, machine room	3
2	Hydraulic oil	damaged, machine room	30 l
3	DR SILL ADJ AND CLEANING LDG	REQUIRED, floor 8	1
4	HYD HOSE 1 M	DMGD, machine room	1
5	Final limit switch, upper	out of adjustment, car top	1
6	Counterweight filler weight	out of adjustment, pit	4
7	Machine room socket	broken, machine room	1
8	Landing door roller	worn, floor 8	2

Pos.	Component	Observation	Units
9	Motor bearing, non-drive end	broken, machine room	1
10	PHASE MONITORING RELAY	FLTY, machine room	1
11	Counterweight guide shoe insert, roller	damaged, pit	3
12	CAR APRON	BRKN, car	1
13	HYD VALVE SEAL KIT	WRN, machine room	1
14	SHAFT LIMIT SW UPPER	NOT WKG, pit	1
15	HALL POS IND	CORR, floor 3	3
16	Lift main switch	loose, machine room	1