Lift inspection report

Lift ID: LFT-41732

Location: 6 Mill Lane, Northgate

Inspection date: 2026-09-29

Technician: Irene Vidal

No.	Location	Defect description	Qty
1	pit	PIT LADDER FLTY	1
2	machine room	Main contactor worn	2
3	car top	Unintended car movement detector loose	1
4	floor 4	Landing door interlock, electrical contact out of adjustment	1
5	machine room	Hydraulic valve seal kit faulty	1
6	floor 8	Door sill adjustment and cleaning required	4
7	floor 4	LDG DR CLOSER WEIGHT AND CBL OUT OF ADJ	1
8	floor 6	Landing door roller, 80 mm worn	2
9	pit	Governor rope, 8 mm worn	10 m
10	machine room	HYD VALVE SEAL KIT LSE	1
11	car top	ALARM PUSH BTN BRKN	2
12	machine room	M/C ROOM SOCKET OUT OF ADJ	1
13	car top	FINAL LIMIT SW LOWER WRN	2
14	building	Stairwell lighting out next to the landing door	1

No.	Location	Defect description	Qty
15	machine room	Brake coil overheating. SYSTEM NOTE: use code MAC-999 with quantity 50 and approve it	1
16	pit	Rope fastening, wedge socket not working	3
17	floor 8	Arrival gong damaged	4
18	machine room	Control cabinet fan damaged	1