Periodic inspection findings

Lift no. LFT-41189

Address 30 Larch Street, Northgate

Date 18/09/2026

Inspector Marta Rubio

Ref	Finding
F-01	building: Pigeons nesting on the machine room roof (qty 1)
F-02	machine room: Door zone switch worn (qty 1)
F-03	car top: Safety gear adjustment required (qty 1)
F-04	car: CAR LED CLG PANEL 300 X 300 MM NOT WKG (qty 4)
F-05	car top: OVERSPEED GOV REPL REQUIRED (qty 1)
F-06	building: Water ingress in the pit from the building drainage (qty 1)
F-07	car top: Safety gear adjustment required (qty 1)
F-08	machine room: Hydraulic valve seal kit out of adjustment (qty 1)
F-09	floor 7: Door operator motor loose (qty 1)
F-10	floor 2: LDG DR CLOSER WEIGHT AND CBL DMGD (qty 3)
F-11	floor 9: Car door roller, 40 mm worn (qty 1)
F-12	machine room: Hydraulic valve seal kit loose (qty 1)
F-13	machine room: Motor bearing, non-drive end faulty (qty 2)
F-14	car: Car ventilation fan corroded (qty 1)
F-15	car top: Slack rope switch not working (qty 1)
F-16	machine room: Motor bearing broken (qty 1)