Periodic inspection findings

Lift no. LFT-42369

Address 88 Mill Lane, Ashdale

Date 14/09/2026

Inspector Pablo Ortega

Ref	Finding
F-01	machine room: RESIDUAL CURRENT DEVICE OUT OF ADJ (qty 2)
F-02	car top: Final limit switch not working (qty 1)
F-03	floor 7: LDG DR CLOSER SPRING OUT OF ADJ (qty 3)
F-04	floor 0: Arrival gong worn (qty 4)
F-05	machine room: MOTOR ENCODER ABSOLUTE NOT WKG (qty 1)
F-06	floor 3: Door operator motor, DC loose (qty 1)
F-07	car top: Overspeed governor, replacement required (qty 1)
F-08	building: Water ingress in the pit from the building drainage (qty 1)
F-09	machine room: Load weighing sensor faulty (qty 1)
F-10	pit: Governor rope broken (qty 30 m)
F-11	machine room: HYD OIL BRKN (qty 40 l)