Lift inspection report

Lift ID: LFT-28532

Location: 4 Orchard Way, Southcliff

Inspection date: 2026-09-06

Technician: Luis Ortega

No.	Location	Defect description	Qty
1	car top	Final limit switch, upper faulty	1
2	floor 8	BRAILLE FLOOR PLATE DMGD	4
3	car top	Safety gear adjustment required	1
4	car	CAR WALL PANEL FLTY	2
5	floor 1	Car door roller, 40 mm not working	3
6	car	Car guide shoe insert faulty	3
7	machine room	Motor encoder, incremental not working	1
8	floor 4	Landing door hanger out of adjustment	4
9	floor 7	Arrival gong broken	3
10	pit	Buffer, car, spring damaged	1
11	pit	BUFFER CAR OIL BRKN	1
12	car top	Overspeed governor, replacement required	1
13	floor 9	Landing key switch faulty	3