Periodic inspection findings

Lift no. LFT-12183

Address 120 Larch Street, Southcliff

Date 09/10/2026

Inspector Ana Navas

Ref	Finding
F-01	machine room: Hydraulic valve seal kit not working (qty 1)
F-02	floor 4: Door gib, car door faulty (qty 3)
F-03	car: CAR OP PANEL PUSH BTN DMGD (qty 3)
F-04	car: Car position indicator, dot-matrix loose (qty 1)
F-05	pit: Governor rope damaged (qty 30 m)
F-06	pit: Pit ladder not working (qty 1)
F-07	pit: Pit stop switch worn (qty 1)
F-08	car top: Overspeed governor, service and test required (qty 1)
F-09	car: Car ventilation fan loose (qty 1)