Branch maintenance form

Unit no.	LFT-79818	**Date of visit**	02 Sep 2026
Site address	40 Orchard Way, Eastbrook	**Engineer**	Luis Vidal

Pos.	Component	Observation	Units
1	Stairwell lighting out next to the landing door	building	1
2	Machine room lighting fitting	not working, machine room	1
3	Floor levelling sensor, magnetic	broken, machine room	1
4	Car floor covering, rubber	damaged, car	3 m2
5	Pigeons nesting on the machine room roof	building	1
6	Light curtain, single-side	faulty, floor 6	1
7	Door gib, car door	faulty, floor 3	1
8	SAFETY GEAR ADJ	REQUIRED, car top	1

Pos.	Component	Observation	Units
9	Slack rope switch	worn, car top	1
10	CAR APRON	LSE, car	1
11	Braille floor plate	worn, floor 6	2
12	Machine room window glass cracked	building	1
13	Light curtain	broken, floor 0	1
14	Car emergency light	worn, car	2
15	Owner asks for an extra stop at the basement	building	1
16	SUSP ROPE 13 MM	FLTY, pit	100 m
17	Buffer, car, spring	corroded, pit	2
18	Brake coil	out of adjustment, machine room	1