Periodic inspection findings

Lift no. LFT-25448

Address 76 Quarry Road, Southcliff

Date 06/09/2026

Inspector Jorge Rubio

Ref	Finding
F-01	car top: EMERG LIGHT BATT NOT WKG (qty 1)
F-02	car top: PIT REFUGE SIGN LSE (qty 2)
F-03	pit: Travelling cable, 24-core not working (qty 60 m)
F-04	machine room: Phase monitoring relay worn (qty 1)
F-05	building: Graffiti on the car walls (qty 1)
F-06	floor 5: Braille floor plate not working (qty 1)
F-07	machine room: RESIDUAL CURRENT DEVICE NOT WKG (qty 2)
F-08	car top: Final limit switch, upper loose (qty 2)
F-09	floor 3: Light curtain, single-side corroded (qty 1)
F-10	pit: TRAV CBL LSE (qty 50 m)
F-11	machine room: Hydraulic hose, 1 m not working (qty 1)
F-12	machine room: BRAKE COIL WRN (qty 2)
F-13	car top: Emergency light battery out of adjustment (qty 1)
F-14	machine room: MOTOR BRG LSE (qty 1)
F-15	car: CAR LED CLG PANEL 300 X 300 MM DMGD (qty 2)
F-16	building: Pigeons nesting on the machine room roof (qty 1)

Ref	Finding
F-17	floor 7: Hall position indicator, dot-matrix damaged (qty 3)
F-18	machine room: Hydraulic cylinder packing worn (qty 1)
F-19	building: Stairwell lighting out next to the landing door (qty 1)
F-20	pit: Governor tension pulley loose (qty 1)