# Branch maintenance form

| | | | |
|---|---|---|---|
| **Unit no.** | LFT-72733 | **Date of visit** | 19 Oct 2026 |
| **Site address** | 116 Harbour Avenue, Fairholm | **Engineer** | Diego Molina |

| Pos. | Component | Observation | Units |
|---|---|---|---|
| 1 | Fuse | faulty, machine room | 1 |
| 2 | Pit ladder | out of adjustment, pit | 1 |
| 3 | Landing call button, up and down | out of adjustment, floor 0 | 2 |
| 4 | Landing door roller | faulty, floor 6 | 2 |
| 5 | Hall position indicator, dot-matrix | damaged, floor 8 | 4 |
| 6 | Car apron | faulty, car | 1 |
| 7 | Hall position indicator, dot-matrix | not working, floor 1 | 4 |
| 8 | GOV ROPE 8 MM | OUT OF ADJ, pit | 120 m |

| Pos. | Component | Observation | Units |
|---|---|---|---|
| 9 | Car operating panel push button | faulty, car | 4 |
| 10 | RAIL LUBR CWT | WRN, pit | 4 |
| 11 | ROPE FASTENING WEDGE SOCKET | LSE, pit | 2 |
| 12 | Slack rope switch | out of adjustment, car top | 1 |
| 13 | M/C ROOM SOCKET | LSE, machine room | 2 |
| 14 | Fuse, 10 A | out of adjustment, machine room | 3 |