Branch maintenance form

Unit no.	LFT-29037	**Date of visit**	14 Oct 2026
Site address	26 Beacon Hill, Ashdale	**Engineer**	Ana Rubio

Pos.	Component	Observation	Units
1	Car roof balustrade	corroded, car top	1
2	Load weighing sensor	loose, machine room	1
3	DR OPERATOR BELT	NOT WKG, floor 6	1
4	Earthing conductor repair	required, machine room	4
5	Door gib	not working, floor 3	3
6	RESIDUAL CURRENT DEVICE	DMGD, machine room	2
7	Owner asks for an extra stop at the basement	building	1
8	Buffer, car, oil	faulty, pit	2

Pos.	Component	Observation	Units
9	Brake coil	not working, machine room	2
10	FUSE 6 A	NOT WKG, machine room	1
11	Door operator belt	out of adjustment, floor 9	1
12	CAR FLOOR COVERING RUBBER	LSE, car	1 m2
13	EMERG LIGHT BATT	OUT OF ADJ, car top	2
14	Safety gear adjustment	required, car top	1
15	Fuse, 16 A	out of adjustment, machine room	3