Branch maintenance form

Unit no.	LFT-46310	**Date of visit**	12 Oct 2026
Site address	30 Chapel Row, Westmere	**Engineer**	Diego Rubio

Pos.	Component	Observation	Units
1	HYD HOSE 1 M	CORR, machine room	2
2	Alarm battery	faulty, car top	2
3	OVERSPEED GOV SERVICE AND TEST	REQUIRED, car top	1
4	Car guide shoe insert	worn, car	2
5	Traction sheave, replacement	required, machine room	1
6	Car ventilation fan	damaged, car	1
7	Car top inspection box	corroded, car	1
8	Unintended car movement detector	loose, car top	1

Pos.	Component	Observation	Units
9	CAR WALL PANEL LAMINATE	WRN, car	3