Periodic inspection findings

Lift no.	LFT-76469
Address	112 Mill Lane, Ashdale
Date	14/10/2026
Inspector	Diego Ferrer

Ref	Finding
F-01	pit: PIT LADDER NOT WKG (qty 1)
F-02	car top: Safety gear adjustment required (qty 1)
F-03	car: Car LED ceiling panel damaged (qty 2)
F-04	car: Car wall panel, laminate faulty (qty 2)
F-05	floor 5: Light curtain, single-side not working (qty 1)
F-06	machine room: Control board relay corroded (qty 3)
F-07	pit: Suspension rope, 10 mm loose (qty 110 m)
F-08	floor 0: Door operator belt loose (qty 1)
F-09	machine room: Residual current device not working (qty 2)
F-10	machine room: TRACTION SHEAVE REPL REQUIRED (qty 1)
F-11	machine room: Gearbox oil change required (qty 1)
F-12	pit: Pit stop switch out of adjustment (qty 1)
F-13	floor 4: DR OPERATOR MOTOR DC FLTY (qty 1)