Periodic inspection findings

Lift no. LFT-31751

Address 75 Orchard Way, Fairholm

Date 10/09/2026

Inspector Luis Rubio

Ref	Finding
F-01	car top: Final limit switch, lower loose (qty 1)
F-02	machine room: Load weighing sensor not working (qty 1)
F-03	car top: Emergency light battery faulty (qty 1)
F-04	machine room: Fuse, 10 A damaged (qty 3)
F-05	floor 0: ARRIVAL GONG CORR (qty 3)
F-06	car top: Overspeed governor, service and test required (qty 1)
F-07	machine room: DR ZONE SW DMGD (qty 1)
F-08	car top: Car roof balustrade worn (qty 1)
F-09	car top: Overspeed governor, replacement required (qty 1)
F-10	building: Graffiti on the car walls (qty 1)
F-11	car: Car wall panel, laminate damaged (qty 4)
F-12	car top: Emergency telephone, GSM module corroded (qty 1)
F-13	floor 9: Landing door interlock, mechanical lock out of adjustment (qty 2)
F-14	floor 6: Braille floor plate worn (qty 1)
F-15	machine room: Door zone switch loose (qty 2)
F-16	machine room: Control board relay worn (qty 4)