Lift inspection report

Lift ID: LFT-37838

Location: 70 Beacon Hill, Southcliff

Inspection date: 2026-09-07

Technician: Ana Rubio

No.	Location	Defect description	Qty
1	machine room	FLOOR LEVELLING SENS OPTICAL NOT WKG	2
2	machine room	Control board relay not working	1
3	car	CAR WALL PANEL LAMINATE WRN	2
4	car top	Final limit switch, upper faulty	1
5	pit	Travelling cable, 40-core worn	20 m
6	pit	ROPE FASTENING WEDGE SOCKET NOT WKG	2
7	machine room	Hydraulic oil not working	110 l
8	machine room	DR ZONE SW LSE	1
9	machine room	BRAKE COIL FLTY	1
10	machine room	Brake coil not working	2
11	machine room	Hydraulic hose, 2 m worn	2
12	floor 0	Hall position indicator, TFT colour faulty	2