Transportation Incident Report R001

DOC-017 | Version 2025 | HISTORICAL

Incident identification

Event EVT-INC-R001-2025. Route R001; origin DC01, destination DEST001, distance 95 km. Historical transportation incident in 2025.

Event timeline

A delivery on route R001 missed the agreed delivery window following an unplanned vehicle breakdown. The Control Tower recorded the delay, notified the receiving site and arranged replacement capacity.

Treatment and precedent

The incident was closed after proof of delivery, carrier root-cause analysis and a preventive maintenance corrective action. Committee follow-up is recorded in DOC-019.