

FICTIONAL DEMO - NOT FOR HARDWARE USE

DEMO-UART-01: First transmit byte

Fictional demonstration erratum. Not a vendor specification.

Affected silicon revision: A. Fixed in silicon revision: B.

Affected section: Reference manual 1.1 UART control register.

The first UART transmit byte may be lost immediately after enable.

Workaround: after setting UART_EN and TX_EN, read UART_STATUS twice before writing the first transmit byte.

This workaround applies only to fictional silicon revision A.