

AUTHORIZED WORKSHOP REPAIR ESTIMATE

Estimate Ref: EST-CLM-001 · Claim Reference: CLM-001

1. Workshop & Vehicle Assessment Details

Workshop Name	Apex Motor Works & Bodycraft	GSTIN / Reg No.	33AABCA1234F1Z5
Claim ID	CLM-001	Vehicle Registration	TN01AB1234
Vehicle Make/Model	Hyundai i20	Estimate Date	23 August 2026
Incident Date (Assessed)	20 August 2026	Assessor Name	V. Sundaram (Chief Surveyor)

2. Itemized Parts & Labour Breakdown

#	Description of Damage / Work	Operation	Parts (₹)	Labour (₹)	Subtotal (₹)
1	Front Bumper Assembly	Replacement	28,000	6,000	34,000
2	Left Headlamp Unit (LED)	Replacement	24,000	4,000	28,000
3	Front Left Fender	Repair & Painting	6,000	10,000	16,000
Total	Grand Total Estimated Repair Cost		₹58,000	₹20,000	₹78,000

3. Workshop Certification

We certify that the above estimate covers only the accidental damage inspected on the vehicle. All replacement parts quoted are OEM standard. This is a synthetic demonstration estimate for ClaimLens.

Authorized Signature: [Apex Motor Works]

Date: 23 August 2026