

AUTHORIZED WORKSHOP REPAIR ESTIMATE

Estimate Ref: EST-CLM-002 · Claim Reference: CLM-002

1. Workshop & Vehicle Assessment Details

Workshop Name	Apex Motor Works & Bodycraft	GSTIN / Reg No.	33AABCA1234F1Z5
Claim ID	CLM-002	Vehicle Registration	TN02CD5678
Vehicle Make/Model	Maruti Baleno	Estimate Date	16 August 2026
Incident Date (Assessed)	14 August 2026	Assessor Name	V. Sundaram (Chief Surveyor)

2. Itemized Parts & Labour Breakdown

#	Description of Damage / Work	Operation	Parts (₹)	Labour (₹)	Subtotal (₹)
1	Front Bumper Assembly	Replacement	26,000	7,000	33,000
2	Right Headlamp Unit	Replacement	22,000	4,000	26,000
3	Bonnet & Grille Panel	Repair & Painting	18,000	15,000	33,000
Total	Grand Total Estimated Repair Cost		₹66,000	₹26,000	₹92,000

3. Workshop Certification

We certify that the above estimate covers only the accidental damage inspected on the vehicle. All replacement parts quoted are OEM standard. This is a synthetic demonstration estimate for ClaimLens.

Authorized Signature: [Apex Motor Works]

Date: 16 August 2026