


MONITOR FEITA-209-2 ASSEMBLY INSTRUCTIONS

REV A



COMPONENTS	QUANTITY
BANANA SOCKET PLUG 4 MM	2
THREADED HEAT-SET INSERT 1/4"-20x6x8	6
BANANA MALE CONECTOR 4 MM	2
MONITOR FEITA-209-2	1
SOCKET HEAD SCREW 1/4-20 x 3/8"	6
TRANSPARENT COVER	1
22 AWG STRANDED WIRE 50 MM	2

SPECIAL ASSEMBLY INSTRUCTIONS

Connect the 4 mm banana male connector to the 4 mm banana socket plug using the specified cable.