**GERO** 30-3000°C

## CONTROL OF THE PROPERTY OF THE

## Program edit

	_	From tp [°C]	To tp	Offset Zone 1	Offset Zone 2	Offset Zone 4	Offset Zone 5	Rate [K/h]	Time [min]	Hold- back [°C]	MFC Ar [I/h]	Valve Bypass	Fast Cooling	Valve Gasinlet Tooling
No	Comment:	[0900]	[°C]	[°C]	[°C]	[-900300]	[°C]	[0180]	[09999]	[0300]	[06000]	Ar [0/I]	[0/1]	[0/I]
1	rampe purge	0	50	+0	+0	+0	+5	0	60	0	1000			
2	plateau purge	50	50	+0	+0	+0	+5	0	120	0	1000			
3	rampe 215	50	215	+0	+0	+0	+5	50	198	0	2000			
4	plateau 215	215	215	+0	+0	+0	+5	0	2880	0	1500			
5	compens.215	215	215	+0	+0	+0	+5	0	1080	0	1500			
6	rampe 404	215	404	+0	+0	+0	+5	50	227	0	2000			
7	plateau 404	404	404	+0	+0	+0	+5	0	2880	0	1500			
8	compens.404	404	404	+0	+0	+0	+5	0	540	0	1500			
9	rampe 644	404	644	+0	+0	+0	+5	50	288	0	2000			
10	plateau 644	644	644	+0	+0	+0	+5	0	3000	0	1500			
11	compens.644	644	644	+0	+0	+0	+5	0	120	0	1500			
12	cool-down 400	644	400	+0	+0	+0	+5	100	146	0	2000			
13	cool-down 50	400	50	+0	+0	+0	+5	100	210	0	2000			
14	holdback four	50	50	+0	+0	+0	+5	0	60	30	2000			
15	plateau purge	50	50	+0	+0	+0	+0	0	1200	0	2000			
16	fin	50	0	+0	+0	+0	+0	0	0	0	0			
17		0	0	+0	+0	+0	+0	0	0	0	0			
18		0	0	+0	+0	+0	+0	0	0	0	0			
19		0	0	+0	+0	+0	+0	0	0	0	0	-		
20		0	0	+0	+0	+0	+0	0	0	0	0			
21		0	0	+0	+0	+0	+0	0	0	0	0			
22		0	0	+0	+0	+0	+0	0	0	0	0			
23		0	0	+0	+0	+0	+0	0	0	0	0			
24		0	0	+0	+0	+0	+0	0	0	0	0			
25		0	0	+0	+0	+0	+0	0	0	0	0			
26		0	0	+0	+0	+0	+0	0	0	0	0			
27		0	0	+0	+0	+0	+0	0	0	0	0			
28		0	0	+0	+0	+0	+0	0	0	0	0			
29		0	0	+0	+0	+0	+0	0	0	0	0			
30		0	0	+0	+0	+0	+0	0	0	0	0			

## -Remarks to program-

	Procedural instructions							
1	coil 11T #111							
2								
3	N.Bourcey							

Calculated runtime	of program
13009	min
Maximal allowed	runtime
min	min

Step description		Calculated runtime:	h	min Current program step:	GLO 750KE/09-1G				File:	20150327_01.csv	
Program number:	0 / 21	Rem. time of program:	h	min Remaining time of current step:	min	Total running time:	255 h	8	min	Operator:	configurator
		· · · · · · · · · · · · · · · · · · ·									

OVERVIEW	PROCESS STEPS	POWER	FILE DATA	PROGRAMS	REPORT	CHART	ADJUSTMENTS	HISTORICAL CHART	SCREENSHOT	
----------	---------------	-------	-----------	----------	--------	-------	-------------	------------------	------------	--