

0	00	EXPRESS 'DB000100' = 'STR1Y1~First external latch input (EXT1)' DB000100 = IB88284; // Unit 8 Axis 01 ORG On (MB075900) STR1Y1 'DB000101' = 'STR1Y2~First external latch input (EXT1)' DB000101 = IB88A84; // Unit 8 Axis 02 ORG On (MB075901) STR1Y2 'DB000102' = 'STR1Z1~First external latch input (EXT1)' DB000102 = IB89284; // Unit 8 Axis 03 ORG On (MB075902) STR1Z1 'DB000103' = 'STR1Z2~First external latch input (EXT1)' DB000103 = IB89A84; // Unit 8 Axis 04 ORG On (MB075903) STR1Z2 'DB000104' = 'SPALX~First external latch input (EXT1)' DB000104 = IB8C284; // Unit 8 Axis 05 ORG On (MB075904) SPALX 'DB000105' = 'SPARX~First external latch input (EXT1)' DB000105 = IB8CA84; // Unit 8 Axis 06 ORG On (MB075905) SPARX 'DB000106' = 0 DB000106 = 0; // Unit 8 Axis 07 ORG On (MB075906) 'DB000107' = 0 DB000107 = 0; // Unit 8 Axis 08 ORG On (MB075907) 'DB000108' = 0 DB000108 = 0; // Unit 8 Axis 09 ORG On (MB075908) 'DB000109' = 0 DB000109 = 0; // Unit 8 Axis 10 ORG On (MB075909) 'DB00010A' = 0 DB00010A = 0; // Unit 8 Axis 11 ORG On (MB07590A) 'DB00010B' = 0 DB00010B = 0; // Unit 8 Axis 12 ORG On (MB07590B) 'DB00010C' = 0 DB00010C = 0; // Unit 8 Axis 13 ORG On (MB07590C) 'DB00010D' = 0 DB00010D = 0; // Unit 8 Axis 14 ORG On (MB07590D) 'DB00010E' = 0 DB00010E = 0; // Unit 8 Axis 15 ORG On (MB07590E) 'DB00010F' = 0 DB00010F = 0; // Unit 8 Axis 16 ORG On (MB07590F)
---	----	--


1	1/42	EXPRESSION 'DB000110' = 0 DB000110 = 0; // Unit 8 Axis 17 ORG On (MB075910) 'DB000111' = 0 DB000111 = 0; // Unit 8 Axis 18 ORG On (MB075911) 'DB000112' = 0 DB000112 = 0; // Unit 8 Axis 19 ORG On (MB075912) 'DB000113' = 0 DB000113 = 0; // Unit 8 Axis 20 ORG On (MB075913) 'DB000114' = 0 DB000114 = 0; // Unit 8 Axis 21 ORG On (MB075914) 'DB000115' = 0 DB000115 = 0; // Unit 8 Axis 22 ORG On (MB075915) 'DB000116' = 0 DB000116 = 0; // Unit 8 Axis 23 ORG On (MB075916) 'DB000117' = 0 DB000117 = 0; // Unit 8 Axis 24 ORG On (MB075917) 'DB000118' = 0 DB000118 = 0; // Unit 8 Axis 25 ORG On (MB075918) 'DB000119' = 0 DB000119 = 0; // Unit 8 Axis 26 ORG On (MB075919) 'DB00011A' = 0 DB00011A = 0; // Unit 8 Axis 27 ORG On (MB07591A) 'DB00011B' = 0 DB00011B = 0; // Unit 8 Axis 28 ORG On (MB07591B) 'DB00011C' = 0 DB00011C = 0; // Unit 8 Axis 29 ORG On (MB07591C) 'DB00011D' = 0 DB00011D = 0; // Unit 8 Axis 30 ORG On (MB07591D) 'DB00011E' = 0 DB00011E = 0; // Unit 8 Axis 31 ORG On (MB07591E) 'DB00011F' = 0 DB00011F = 0; // Unit 8 Axis 32 ORG On (MB07591F)
---	------	---

2		FOR	[W]var DW00040 ---	[W]Init 00000	[W]Max 00031	[W]Step 00001			
3	NL	2			EXPRESSION 'I' = 'DW00040' I = DW00040;				
4	NL	DB000100i 2 ---	TON[10ms]	[W]Set 00000	[W]Count DW00090i ---			MB075900i Unit 8 Axis 0 1 ORG On (MB075900)-	
5		END_FOR							

[MB075900]
H20.02/1138
GET_IR/0139

H20.02/1367
GET_IR/0548

GET_IR/0121
GET_IR/1031



[MB075920]
.../0199i
GET_IR/1033

[MB075410]
.../0203i
L90.28/1172

Sensor Input (-OT Sensor)									
13	26/212			EXPRESSION 'DB000140' = 'STR1Y1~Reverse run prohibited input (N_OT)' 'DB000140' = IB88283; // Unit 8 Axis 01 -OT On (MB075940) STR1Y1 'DB000141' = 'STR1Y2~Reverse run prohibited input (N_OT)' 'DB000141' = IB88A83; // Unit 8 Axis 02 -OT On (MB075941) STR1Y2 'DB000142' = 'STR1Z1~Reverse run prohibited input (N_OT)' 'DB000142' = IB89283; // Unit 8 Axis 03 -OT On (MB075942) STR1Z1 'DB000143' = 'STR1Z2~Reverse run prohibited input (N_OT)' 'DB000143' = IB89A83; // Unit 8 Axis 04 -OT On (MB075943) STR1Z2 'DB000144' = 'SPALX~Reverse run prohibited input (N_OT)' 'DB000144' = IB8C283; // Unit 8 Axis 05 -OT On (MB075944) SPALX 'DB000145' = 'SPARX~Reverse run prohibited input (N_OT)' 'DB000145' = IB8CA83; // Unit 8 Axis 06 -OT On (MB075945) SPARX 'DB000146' = 0 'DB000146' = 0; // Unit 8 Axis 07 -OT On (MB075946) 'DB000147' = 0 'DB000147' = 0; // Unit 8 Axis 08 -OT On (MB075947) 'DB000148' = 0 'DB000148' = 0; // Unit 8 Axis 09 -OT On (MB075948) 'DB000149' = 0 'DB000149' = 0; // Unit 8 Axis 10 -OT On (MB075949) 'DB00014A' = 0 'DB00014A' = 0; // Unit 8 Axis 11 -OT On (MB07594A) 'DB00014B' = 0 'DB00014B' = 0; // Unit 8 Axis 12 -OT On (MB07594B) 'DB00014C' = 0 'DB00014C' = 0; // Unit 8 Axis 13 -OT On (MB07594C) 'DB00014D' = 0 'DB00014D' = 0; // Unit 8 Axis 14 -OT On (MB07594D) 'DB00014E' = 0 'DB00014E' = 0; // Unit 8 Axis 15 -OT On (MB07594E) 'DB00014F' = 0 'DB00014F' = 0; // Unit 8 Axis 16 -OT On (MB07594F)					
14	27/234			EXPRESSION 'DB000150' = 0 'DB000150' = 0; // Unit 8 Axis 17 -OT On (MB075950) 'DB000151' = 0 'DB000151' = 0; // Unit 8 Axis 18 -OT On (MB075951) 'DB000152' = 0 'DB000152' = 0; // Unit 8 Axis 19 -OT On (MB075952) 'DB000153' = 0 'DB000153' = 0; // Unit 8 Axis 20 -OT On (MB075953) 'DB000154' = 0 'DB000154' = 0; // Unit 8 Axis 21 -OT On (MB075954) 'DB000155' = 0 'DB000155' = 0; // Unit 8 Axis 22 -OT On (MB075955) 'DB000156' = 0 'DB000156' = 0; // Unit 8 Axis 23 -OT On (MB075956) 'DB000157' = 0 'DB000157' = 0; // Unit 8 Axis 24 -OT On (MB075957) 'DB000158' = 0 'DB000158' = 0; // Unit 8 Axis 25 -OT On (MB075958) 'DB000159' = 0 'DB000159' = 0; // Unit 8 Axis 26 -OT On (MB075959) 'DB00015A' = 0 'DB00015A' = 0; // Unit 8 Axis 27 -OT On (MB07595A) 'DB00015B' = 0 'DB00015B' = 0; // Unit 8 Axis 28 -OT On (MB07595B) 'DB00015C' = 0 'DB00015C' = 0; // Unit 8 Axis 29 -OT On (MB07595C) 'DB00015D' = 0 'DB00015D' = 0; // Unit 8 Axis 30 -OT On (MB07595D) 'DB00015E' = 0 'DB00015E' = 0; // Unit 8 Axis 31 -OT On (MB07595E) 'DB00015F' = 0 'DB00015F' = 0; // Unit 8 Axis 32 -OT On (MB07595F)					
15	28/302	FOR	[W]Var DW00040 ---	[W]Init 00000	[W]Max 00031	[W]Step 00001			
16	29/306	NL 2			EXPRESSION 'I' = 'DW00040' I = DW00040;				
17	30/308	NL 2	DB000140i ---				MB075940i Unit8 Axis01 -OT Sensor	[MB075940] .../0310i GET_IR/0550	GET_IR/0123 GET_IR/0141
18	32/310	NL 2	MB075940i Unit8 Axis01 -OT Sensor	MB000001 Stopping	TON[10ms]	[W]Set CW00103 ---	[W]Count DW00154i ---	MB00005C Running AB S Search	[MB075430] .../0314i L90.28/0948
			MB075430i Lv2_UNIT8 AXIS1 OT- ALARM						
			MB000059 Jog Driving	MB027841 Jog		MB00006F Pls:Reset	MB000001 Stopping	MB075430i Lv2_UNIT8 AXIS1 OT- ALARM	
			MB000059 Jog Driving						
19	33/322		END_FOR						
20	34/323				END				