



	H30.15:Work Alarm												
	Panel Set Condition												
	SCT												
0	0/0	MB000181								MB002800	[MB002800] H30.22/0163 H30.22/0299	H30.22/0166	H30.22/0167
		SCT Use								Work Condi on : SCT Ca rry In			
		MB000181											
		SCT Use											
1	3/3	MB000181		MB066900						MB002801	[MB002801] H30.20/0048 H30.22/0184	H30.22/0180	H30.22/0183
		SCT Use		MBT Glass Detect Sens or						Work Condi on : SCT Mai n Buffer Tab-			
				MB000800									
				MCTAG_Idli ng									
				MB00000F									
				Debug									
		MB000181											
		SCT Use											
2	5/5	MB000181		MB071900		MB071888				MB002802	[MB002802] H30.20/0042 H30.22/0201	H30.22/0197	H30.22/0200
		SCT Use		Unit7 Detect 1 On (Sens or) MTR Gla-		[Response] MTR Vacuu m All On				Work Condi on : SCT Mai n Transfer			
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											
3	13/13	MB000181		MB09018F						MB002803	[MB002803] H30.20/0036 H30.22/0218	H30.22/0214	H30.22/0217
		SCT Use		Sensor : SC T Fix Table All Vacuum-						Work Condi on : SCT Scr ibe Fix Table			
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											
4	20/20	MB000181		MB09018E						MB002804	[MB002804] H30.20/0029 H30.22/0235	H30.22/0231	H30.22/0234
		SCT Use		[Sensor] SC T Scribe Ch uck All Vac-						Work Condi on : SCT Scr ibe Chuck Y			
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											
5	25/25	MB000181		MB05684F						MB002805	[MB002805] H30.20/0023 H30.22/0252	H30.22/0248	H30.22/0251
		SCT Use		[Sensor] SC T Break Tabl e Vacuum A-						Work Condi on : SCT Bre ak Table			
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											
6	30/30	MB000181		MB076900		MB076888				MB002806	[MB002806] H30.20/0017 H30.22/0269	H30.22/0265	H30.22/0268
		SCT Use		(Sensor) ST R1 Glass De tect		[Response] STR1 Vacuu m All On				Work Condi on : SCT Sti ck Transfer-			
				MB00000F									
				Debug									
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											
7	31/31	MB000181		MB081888						MB002807	[MB002807] H30.20/0011 H30.22/0286	H30.22/0282	H30.22/0285
		SCT Use		[Response] SBT Vacuu m All On						Work Condi on : SCT Sti ck Buffer T-			
				MB000800									
				MCTAG_Idli ng									
		MB000181											
		SCT Use											



[MB002808]
H30.20/0002



[MB002809]
H30.20/0005

Timer Setting												
26	126/126				EXPRESSION				[DW00031] ../0186w [DW00032] ../0193w [DW00033] ../0200w [DW00034] ../0207w [DW00035] ../0214w [DW00036] ../0221w [DW00037] ../0228w [DW00038] ../0235w [DW00039] ../0241w [DW00040] ../0247w [DW00041] ../0253w [DW00042] ../0259w [DW00043] ../0265w [DW00044] ../0271w [DW00045] ../0277w [DW00046] ../0283w [DW00047] ../0289w [DW00048] ../0295w [DW00049] ../0301w [DW00050] ../0307w [DW00051] ../0313w [DW00052] ../0319w [DW00053] ../0325w [DW00054] ../0331w [DW00055] ../0337w			
					'DW00030' = 100 DW00030 = 100; // SCT Carry In 'DW00031' = 100 DW00031 = 100; // SCT Main Buffer Table 'DW00032' = 100 DW00032 = 100; // SCT Main Transfer 'DW00033' = 100 DW00033 = 100; // SCT Scribe Fix Table 'DW00034' = 100 DW00034 = 100; // SCT Scribe Chuck Y 'DW00035' = 100 DW00035 = 100; // SCT Break Table 'DW00036' = 100 DW00036 = 100; // SCT Stick Transfer 1 'DW00037' = 100 DW00037 = 100; // SCT Stick Buffer Table 'DW00038' = 100 DW00038 = 100; // LCCT Stick Transfer 2 'DW00039' = 100 DW00039 = 100; // RCCT Stick Transfer 2 'DW00040' = 100 DW00040 = 100; // LCCT Left Scribe Fix Table 'DW00041' = 100 DW00041 = 100; // LCCT Left Scribe Chuck Y 'DW00042' = 100 DW00042 = 100; // LCCT Left Break Table 'DW00043' = 100 DW00043 = 100; // LCCT Left Carry Out 'DW00044' = 100 DW00044 = 100; // LCCT Right Scribe Fix Table 'DW00045' = 100 DW00045 = 100; // LCCT Right Scribe Chuck Y 'DW00046' = 100 DW00046 = 100; // LCCT Right Break Table 'DW00047' = 100 DW00047 = 100; // LCCT Right Carry Out 'DW00048' = 100 DW00048 = 100; // RCCT Left Scribe Fix Table 'DW00049' = 100 DW00049 = 100; // RCCT Left Scribe Chuck Y 'DW00050' = 100 DW00050 = 100; // RCCT Left Break Table 'DW00051' = 100 DW00051 = 100; // RCCT Left Carry Out 'DW00052' = 200 DW00052 = 200; // RCCT Right Scribe Fix Table 'DW00053' = 100 DW00053 = 100; // RCCT Right Scribe Chuck Y 'DW00054' = 100 DW00054 = 100; // RCCT Right Break Table 'DW00055' = 100 DW00055 = 100; // RCCT Right Carry Out							
27	127/178	SCT							[MB002960] H30.22/0172w	H50.46/1366		
		MB00000F Debug	MB002000 P Work : SCT Carry In	TON[10ms]	[W]Set DW00030 ---	[W]Count DW00230 ---		MB002960 Ⓢ P Work Alarm : SCT Carry In				
28	131/183	MB002480	MB002001 P Work : SCT Main Buffer Table	TON[10ms]	[W]Set DW00031 ---	[W]Count DW00231 ---		MB002961 Ⓢ P Work Alarm : SCT Main Buffer Table	[MB002961] H30.22/0189w [MB002480] ../0183 H30.20/0046 H80.11/0303w	H50.46/1372	H30.10/0613 H30.20/0051w	H30.10/0619 H30.23/00251w
		Work Move : SCT Carry In → SCT Main- MB002161 Force Work : SCT Main Buffer Table						MB002480 Ⓡ Work Move : SCT Carry In → SCT Main-				
29	137/190	MB002481	MB002002 p Work : SCT Main Transfer	TON[10ms]	[W]Set DW00032 ---	[W]Count DW00232 ---		MB002962 Ⓢ P Work Alarm : SCT Main Transfer	[MB002962] H30.22/0206w [MB002481] ../0190 H30.20/0040	H50.47/1722	H30.10/0605 H30.20/0045w	H30.10/0611
		Work Move : SCT Main Buffer Table → - MB002162 Force Work : SCT Main Transfer						MB002481 Ⓡ Work Move : SCT Main Buffer Table → -				
30	143/197	MB002482	MB002003 P Work : SCT Scribe Fix Table	TON[10ms]	[W]Set DW00033 ---	[W]Count DW00233 ---		MB002963 Ⓢ P Work Alarm : SCT Scribe Fix Table	[MB002963] H30.22/0223w [MB002482] ../0197 H30.20/0034	H50.42/3034	H30.10/0597 H30.20/0039w	H30.10/0603
		Work Move : SCT Main Transfer → SCT- MB002163 Force Work : SCT Scribe Fix Table						MB002482 Ⓡ Work Move : SCT Main Transfer → SCT-				
31	149/204	MB002483	MB002004 P Work : SCT Scribe Chuck Y	TON[10ms]	[W]Set DW00034 ---	[W]Count DW00234 ---		MB002964 Ⓢ P Work Alarm : SCT Scribe Chuck Y	[MB002964] H30.22/0240w [MB002483] ../0204 H30.20/0027	H50.42/3040	H30.10/0589 H30.20/0032w	H30.10/0595
		Work Move : SCT Scribe Fix Table → S- MB002164 Force Work : SCT Scribe Chuck Y						MB002483 Ⓡ Work Move : SCT Scribe Fix Table → S-				
32	155/211	MB002484	MB002005 P Work : SCT Break Table	TON[10ms]	[W]Set DW00035 ---	[W]Count DW00235 ---		MB002965 Ⓢ P Work Alarm : SCT Break Table	[MB002965] H30.22/0257w [MB002484] ../0211 H30.10/0559 H30.20/0021	H50.44/1526	H30.10/0547 H30.10/0564 H30.20/0026w	H30.10/0553 H30.10/0587
		Work Move : SCT Scribe Chuck Y → S- MB002165 Force Work : SCT Break Table						MB002484 Ⓡ Work Move : SCT Scribe Chuck Y → S-				

33 101/218	MB002485	MB002006	TON[10ms]	[W]Set DW00036 ---	[W]Count DW00236 ---	MB002966 Ⓢ	[MB002966] H30.22/0274w [MB002485] ../0218 H30.10/0545	H50.48/1540 H30.10/0526 H30.20/0015	H30.10/0532 H30.20/0020w
	Work Move : SCT Break Table → SCT S-	P Work : SCT Stick Transfer 1				P Work Alarm : SCT Stick Transfer 1			
	MB002166					MB002485 Ⓡ			
34 161/225	Force Work : SCT Stick Transfer 1					Work Move : SCT Break Table → SCT S-			
	MB002486	MB002007	TON[10ms]	[W]Set DW00037 ---	[W]Count DW00237 ---	MB002967 Ⓢ	[MB002967] H30.22/0291w [MB002486] ../0225 H30.10/0517 H30.20/0014w	H50.49/1439 H30.10/0504 H30.10/0524	H30.10/0510 H30.20/0009
	Work Move : SCT Stick Transfer 1 → S-	P Work : Stick Buffer Table				P Work Alarm : SCT Stick Buffer Table			
	MB002167					MB002486 Ⓡ			
	Force Work : SCT Stick Buffer Table					Work Move : SCT Stick Transfer 1 → S-			
LCCT									
35 171/232	MB002487	MB002008	TON[10ms]	[W]Set DW00038 ---	[W]Count DW00238 ---	MB002968 Ⓢ			
	Work Move : SCT Stick Buffer Table → -	P Work : LCCT Stick Transfer 2				P Work Alarm : LCCT Stick Transfer-			
	MB002168								
36 178/238	Force Work : LCCT Stick Transfer 2								
	MB002489	MB00200A	TON[10ms]	[W]Set DW00039 ---	[W]Count DW00239 ---	MB00296A Ⓢ			
	Work Move : LCCT Stick Transfer 2 → -	P Work : LCCT Left Scribe Fix Table				P Work Alarm : LCCT Left Scribe Fix-			
37 183/244	MB00216A								
	Force Work : LCCT Left Scribe Fix Table								
	MB00248A	MB00200B	TON[10ms]	[W]Set DW00040 ---	[W]Count DW00240 ---	MB00296B Ⓢ			
38 188/250	Work Move : LCCT Left Scribe Fix Table	P Work : LCCT Left Scribe Chuck Y				P Work Alarm : LCCT Left Scribe Ch-			
	MB00216B								
	Force Work : LCCT Left Scribe Chuck-								
39 193/256	MB00248B	MB00200C	TON[10ms]	[W]Set DW00041 ---	[W]Count DW00241 ---	MB00296C Ⓢ			
	Work Move : LCCT Left Scribe Chuck Y-	P Work : LCCT Left Break Table				P Work Alarm : LCCT Left Break Tab-			
	MB00216C								
40 198/262	Force Work : LCCT Left Break Table								
	MB00248C	MB00200D	TON[10ms]	[W]Set DW00042 ---	[W]Count DW00242 ---	MB00296D Ⓢ			
	Work Move : LCCT Left Break Table ?	P Work : LCCT Left Carry Out				P Work Alarm : LCCT Left Carry Out			
41 203/268	MB00216D								
	Force Work : LCCT Left Carry Out								
	MB00248D	MB00200E	TON[10ms]	[W]Set DW00043 ---	[W]Count DW00243 ---	MB00296E Ⓢ			
42 208/274	Work Move : LCCT Stick Transfer 2 → -	P Work : LCCT Right Scribe Fix Table				P Work Alarm : LCCT Right Scribe F-			
	MB00216E								
	Force Work : LCCT Right Scribe Fix -								
43 213/274	MB00248E	MB00200F	TON[10ms]	[W]Set DW00044 ---	[W]Count DW00244 ---	MB00296F Ⓢ			
	Work Move : LCCT Right Scribe Fix Table	P Work : LCCT Right Scribe Chuck Y				P Work Alarm : LCCT Right Scribe -			
	MB00216F								
44 218/274	Force Work : LCCT Right Scribe Chuck-								
	MB00248F	MB002010	TON[10ms]	[W]Set DW00045 ---	[W]Count DW00245 ---	MB002970 Ⓢ			
	Work Move : LCCT Right Scribe Chuck -	P Work : LCCT Right Break Table				P Work Alarm : LCCT Right Break T-			
45 223/274	MB002170								
	Force Work : LCCT Right Break Table								
				H30.15 : Panel Existence Alarm				P00005	

