

H20.04:PDT Tag										
0	0/0	IF	'SCT PDT Key Switch (KEY NO)' 'SCT PDT Key Switch (Key NO) (R)' 'SCT PDT Key Switch (Key NO) (R)' MB030890 MB030891 MB030892							
1	1/6	NL 2				STORE	[WLFQD]Src 00000	[WLFQD]Dest MW01820 Axis Index	[MW01820] .../0014w .../0044w	
2	2/8	NL 2	MB018120 [PDT→PC] J OG ON	MB1150009 [Link : S1] T eaching Key On	MB1170009 [Link : S2-1] Teaching Ke y On	MB1180009 [Link : S2-2] Teaching Ke y On				
			EXPRESSION 'Axis Index' = 'MW01802' MW01820 = MW01802; // Axis Index							
3	7/16	NL 2				COPYW	[W]Src MW01800 ---	[W]Dest MW20000 [PCTAG]PC Command C ode	[MW20000] H40.50/0082w	
4	8/19	NL 2	MB01812D [PDT→PC] J OG SPEED (0:LOW 1:H-					MB200128 [PCTAG]PC JOG High S peed	[MB200128] H40.50/0094	
5	10/21	NL 2	MB01812E [PDT→PC] J OG DIRECTI ON (0:CW 1-					MB200129 [PCTAG]PC JOG CW/CC W	[MB200129] H40.50/0013	
6	12/23	NL 2	MB018121 [PDT→PC] S ERVO ON					MB205415 [Btn_In]Serv o On	[MB205415] H20.30/0090	
7	14/25	NL 2	MB018123 [PDT→PC] S ERVO OFF					MB205414 [Btn_In]Serv o Off	[MB205414] H20.30/0071	
8	16/27	NL 2	MB216815 [Btn_Out]Ser vo On					MB018122 [PDT→PC] S ERVO ON L AMP		
9	18/29	NL 2	MB212814 ---					MB018124 [PDT→PC] S ERVO OFF LAMP		
10	20/31	NL 2	MB21281F ---					MB018126 [PDT→PC] A LARM LAMP		
11	22/33	NL 2	MB018125 [PDT→PC] A LARM RESE T					MB20541F [Btn_In]Alar m Reset	[MB20541F] H80.18/0583	
12	24/35	NL 2	Touch Monitoring							
			!= [WLFQD]SrcA MW01820 Axis Index	[WLFQD]SrcB DW00022 ---	!= [WLFQD]SrcA MW01820 Axis Index	[WLFQD]SrcB 00000 ---			[DW00022] .../0036 .../0061	
					COPYW	[W]Src MW01820 Axis Index	[W]Dest DW00022 ---	[W]Width 00001	.../0049 .../0065	
13	27/48	NL 2	!= [WLFQD]SrcA MW02782 Axis Index	[WLFQD]SrcB DW00022 ---	!= [WLFQD]SrcA MW02782 Axis Index	[WLFQD]SrcB 00000 ---			[DW00022] .../0036 .../0061	
					COPYW	[W]Src MW02782 Axis Index	[W]Dest DW00022 ---	[W]Width 00001	.../0045w .../0065	
14	30/61	NL 2	EXPRESSION 'I' = (DW00022-1)*2 I = (DW00022-1)*2; 'J' = (DW00022-1)*100 J = (DW00022-1)*100; 'ML01814' = 'ML53920' ML01814 = ML53920; // AXIS Position 'ML01816' = 'ML40002' ML01816 = ML40002; // JOG Low Speed 'ML01818' = 'ML40000' ML01818 = ML40000; // JOG High Speed							
			PDT No. 1:SCT 2:LCCT 3:RCCT							
15	31/75	NL 2	MB000181 SCT Use			STORE	[WLFQD]Src 00001	[WLFQD]Dest MW01813 ---	[MW01813] .../0083w .../0088w	
16	33/80	NL 2	MB000182 LCCT Use			STORE	[WLFQD]Src 00002	[WLFQD]Dest MW01813 ---	[MW01813] .../0078w .../0088w	
17	35/85	NL 2	MB000183 RCCT Use			STORE	[WLFQD]Src 00003	[WLFQD]Dest MW01813 ---	[MW01813] .../0078w .../0083w	
18	37/90	NL 2	END_IF							
19	38/91	NL 2	END							