

H30.23:Glass Tracking Data Move									
0	0/0	FOR	[W]Var DW00020 ---	[W]Init 00000	[W]Max 00024	[W]Step 00001			
1	1/4	NL	EXPRESSION 'I' = 'DW00020' I = DW00020;						
2	2/6	NL	MB205020i [PC-TAG] Work Move : SCT Carry In → - MB1155240i MB000181 --- SCT Use MB1175240i MB000182 --- LCCT Use MB1185240i MB000183 --- RCCT Use					DB000100i [PC-TAG] Work Move : Carry In → Pre Al-	[DB000100] .../0023i
3	10/14		END_FOR						
4	11/15		IF	'SCT Use' MB000181					
5	12/17	NL	FOR	[W]Var DW00020 ---	[W]Init 00000	[W]Max 00006	[W]Step 00001		
6	13/21	NL	EXPRESSION 'I' = 'DW00020' I = DW00020;						
7	14/23	NL	DB000100i DB000000i [PC-TAG] Work Move : Carry In → Pre Al- MB002480i Work Move : SCT Carry In → SCT Main-						[MB002480] H30.10/0613 H30.15/0189w H80.11/0303w
8	17/26	NL	DB000100i MB002001i [PC-TAG] Work Move : Carry In → Pre Al- P Work : SCT Main Buffer Table MB214420i [MCTAG] Work Move : SCT Carry In → -						
9	20/29	NL	END_FOR						
10	21/30	NL	DB00010F DB00000F [PC-TAG] Work Move : Stick TR → Scri- MB00248F Work Move : LCCT Right Scribe Chuck -						[MB00248F] H30.10/0332
11	24/33	NL	DB00010F MB00200D [PC-TAG] Work Move : Stick TR → Scri- P Work : LCCT Left Carry Out MB21062F ---						
12	27/36		END_IF						
13	28/37		IF	'LCCT Use' MB000182					
14	29/39	NL	DB000107 DB000007 [PC-TAG] Work Move : Scribe Feed → - MB002487 Work Move : SCT Stick Buffer Table → -						[MB002487] H30.10/0502 H30.20/0007w
15	32/42	NL	DB000107 MB002008 [PC-TAG] Work Move : Scribe Feed → - P Work : LCCT Stick Transfer 2 MB214427 [MCTAG] Work Move : SCT Stick Buffer -						
16	33/43	NL	FOR	[W]Var DW00020 ---	[W]Init 00000	[W]Max 00007	[W]Step 00001		
17	36/49	NL	EXPRESSION 'I' = 'DW00020' I = DW00020;						
18	37/51	NL	DB000109i DB000009i [PC-TAG] Work Move : Lower Table → - MB002489i Work Move : LCCT Stick Transfer 2 → -						[MB002489] H30.10/0478
19	40/54	NL	DB000109i MB00200A [PC-TAG] Work Move : Lower Table → - P Work : LCCT Left Scribe Fix Table MB214429i [MCTAG] Work Move : LCC T Stick Trans-						
20	43/57	NL	END_FOR						
21	44/58		END_IF						
22	45/59		IF	'RCCT Use' MB000183					
23	48/61	NL	DB000108 DB000008 [PC-TAG] Work Move : Scribe → Lower - MB002488 Work Move : SCT Stick Buffer Table → -						[MB002488] H30.10/0250 H30.20/0008w

.../0026i

H30.10/0619
H30.20/0046H30.15/0183
H30.20/0051w

H30.15/0274

H30.15/0232
H80.40/0013H30.20/0000
H80.40/0015w

H30.15/0238

H30.15/0286
H80.40/0009H30.20/0003
H80.40/0011w

24	NL	DB000108	MB002009						MB214428
49/64	2	PC-TAG] Wo k Move : Scri be → Lower -	P Work : RC CT Stick Tra nsfer 2						[MCTAG]Wor k Move : SCT Stick Buffer -
25	NL	FOR	[W]Var DW00020 ---	[W]init 00000	[W]Max 00007	[W]Step 00001			
50/67	2								
26	NL				EXPRESSION				
53/71	3				'I' = 'DW00020' I = DW00020;				
27	NL	DB000111i	DB000011i						MB002491i
54/73	3	PC-TAG] Wo k Move : Scri be → Lower -							Work Move : RCCT Stick T ransfer 2 → -
28	NL	DB000111i	MB002012i						MB214431i
57/76	3	PC-TAG] Wo k Move : Scri be → Lower -	P Work : RC CT Left Scri be Fix Table						[MCTAG]Wor k Move : RCC T Stick Trans-
29	NL	END_FOR							
60/79	2								
30	NL	END_IF							
61/80									
31	NL				END				
62/81									

[MB002491]
H30.10/0226

H30.15/0292