

L:L-Scan Main									
0						SEE	L10	Name	
								IO Signal	
1						SEE	L20	Name	
								PC Interface	
2						SEE	L30	Name	
								Monitor	
3						SEE	L40	Name	
								Axis Control	
4						SEE	L60	Name	
								Jog/Step Enable	
5						SEE	L80	Name	
								PC Interface2 (BTN Eanble Inte rlock)	
6						SEE	L90	Name	
								Alarm	
7						END			