

0	MB00000F Debug					DB000000 ---	[DB000000] .../0008 .../0014 .../0020 .../0026 .../0032 .../0038 .../0044 .../0050 .../0056 .../0062 .../0068 .../0070	.../0010 .../0016 .../0022 .../0028 .../0034 .../0040 .../0046 .../0052 .../0058 .../0064 .../0066	.../0012 .../0018 .../0024 .../0030 .../0036 .../0042 .../0048 .../0054 .../0060
1				SETW	[W]Dest MW90180 ---	[W]Data HFFFF ---	[W]Width 00016 ---	[MW90180] .../0077w	L40.40/0091i
2				SETW	[W]Dest MW90308 ---	[W]Data HFFFF ---	[W]Width 00016 ---	[MW90308] .../0080w	L40.40/0168i
	Jog(-) Enable 조건 81 Axis (SP) DL00010 ~ DL00018								
3	DB000000 ---						MB901800 ---		
	82 Axis (SP) DL00020 ~ DL00028								
4	DB000000 ---						MB901810 ---		
	83 Axis (SP) DL00030 ~ DL00038								
5	DB000000 ---						MB901820 ---		
	84 Axis (SP) DL00040 ~ DL00048								
6	DB000000 ---						MB901830 ---		
	85 Axis (SP) DL00050 ~ DL00058								
7	DB000000 ---						MB901840 ---		
	86 Axis (SP) DL00060 ~ DL00068								
8	DB000000 ---						MB901850 ---		
	87 Axis (SP) DL00070 ~ DL00078								
9	DB000000 ---						MB901860 ---		
	88 Axis (SP) DL00080 ~ DL00088								
10	DB000000 ---						MB901870 ---		
	89 Axis (SP) DL00090 ~ DL00098								
11	DB000000 ---						MB901880 ---		
	90 Axis (SP) DL00100 ~ DL00108								
12	DB000000 ---						MB901890 ---		
	91 Axis (SP) DL00110 ~ DL00118								
13	DB000000 ---						MB901900 ---		
	92 Axis (SP) DL00120 ~ DL00128								
14	DB000000 ---						MB901910 ---		
	93 Axis (SP) DL00130 ~ DL00138								
15	DB000000 ---						MB901920 ---		
	94 Axis (SP) DL00140 ~ DL00148								
16	DB000000 ---						MB901930 ---		

L60.15 : Jog Btn Enable (8 Circuit)

P00001

	95 Axis (SP) DL000150 ~ DL000158					
17	DB0000000					MB901940
32/38						
	96 Axis (SP) DL000160 ~ DL000168					
18	DB0000000					MB901950
34/38						
	Jog(+) Enable 조건 81 Axis (SP) DL000210 ~ DL000218					
19	DB0000000					MB903080
36/40						
	82 Axis (SP) DL000220 ~ DL000228					
20	DB0000000					MB903090
38/42						
	83 Axis (SP) DL000230 ~ DL000238					
21	DB0000000					MB903100
40/44						
	84 Axis (SP) DL000240 ~ DL000248					
22	DB0000000					MB903110
42/46						
	85 Axis (SP) DL000250 ~ DL000258					
23	DB0000000					MB903120
44/48						
	86 Axis (SP) DL000260 ~ DL000268					
24	DB0000000					MB903130
46/50						
	87 Axis (SP) DL000270 ~ DL000278					
25	DB0000000					MB903140
48/52						
	88 Axis (SP) DL000280 ~ DL000288					
26	DB0000000					MB903150
50/54						
	89 Axis (SP) DL000290 ~ DL000298					
27	DB0000000					MB903160
52/56						
	90 Axis (SP) DL00300 ~ DL00308					
28	DB0000000					MB903170
54/58						
	91 Axis (SP) DL00310 ~ DL00318					
29	DB0000000					MB903180
56/60						
	92 Axis (SP) DL00320 ~ DL00328					
30	DB0000000					MB903190
58/62						
	93 Axis (SP) DL00330 ~ DL00338					
31	DB0000000					MB903200
60/64						
	94 Axis (SP) DL00340 ~ DL00348					
32	DB0000000					MB903210
62/66						
	95 Axis (SP) DL00350 ~ DL00358					
33	DB0000000					MB903220
64/68						

