

	L60.16:Jog Btn Enable (9 Circuit)								
0	0/0	MB00000F					DB000000	[DB000000]	
		Debug					---	.../0008	.../0010
								.../0014	.../0016
								.../0020	.../0022
								.../0026	.../0028
								.../0032	.../0034
								.../0038	.../0040
								.../0044	.../0046
								.../0050	.../0052
								.../0056	.../0058
								.../0062	.../0064
								.../0068	.../0070
1	2/2				SETW	[W]Dest MW90196	[W]Data HFFFF	[W]Width 00016	[MW90196]
						---			.../0077w
2	3/3				SETW	[W]Dest MW90324	[W]Data HFFFF	[W]Width 00016	[MW90324]
						---			.../0080w
		Jog(-) Enable 조건							
		97 Axis (SP)							
		DL00010 ~ DL00018							
3	4/8	DB000000					MB901960		
		---					---		
		98 Axis (SP)							
		DL00020 ~ DL00028							
4	6/10	DB000000					MB901970		
		---					---		
		99 Axis (SP)							
		DL00030 ~ DL00038							
5	8/12	DB000000					MB901980		
		---					---		
		100 Axis (SP)							
		DL00040 ~ DL00048							
6	10/14	DB000000					MB901990		
		---					---		
		101 Axis (SP)							
		DL00050 ~ DL00058							
7	12/16	DB000000					MB902000		
		---					---		
		102 Axis (SP)							
		DL00060 ~ DL00068							
8	14/18	DB000000					MB902010		
		---					---		
		103 Axis (SP)							
		DL00070 ~ DL00078							
9	16/20	DB000000					MB902020		
		---					---		
		104 Axis (SP)							
		DL00080 ~ DL00088							
10	18/22	DB000000					MB902030		
		---					---		
		105 Axis (SP)							
		DL00090 ~ DL00098							
11	20/24	DB000000					MB902040		
		---					---		
		106 Axis (SP)							
		DL000100 ~ DL000108							
12	22/26	DB000000					MB902050		
		---					---		
		107 Axis (SP)							
		DL000110 ~ DL000118							
13	24/28	DB000000					MB902060		
		---					---		
		108 Axis (SP)							
		DL000120 ~ DL000128							
14	26/30	DB000000					MB902070		
		---					---		
		109 Axis (SP)							
		DL000130 ~ DL000138							
15	28/32	DB000000					MB902080		
		---					---		
		110 Axis (SP)							
		DL000140 ~ DL000148							
16	30/34	DB000000					MB902090		
		---					---		
						L60.16 : Jog Btn Enable (9 Circuit)			
						P00001			

	111 Axis (SP) DL000150 ~ DL000158					
17	DB0000000					MB902100
32/38						
	112 Axis (SP) DL000160 ~ DL000168					
18	DB0000000					MB902110
34/38						
	Jog(+) Enable 조건 97 Axis (SP) DL000210 ~ DL000218					
19	DB0000000					MB903240
36/40						
	98 Axis (SP) DL000220 ~ DL000228					
20	DB0000000					MB903250
38/42						
	99 Axis (SP) DL000230 ~ DL000238					
21	DB0000000					MB903260
40/44						
	100 Axis (SP) DL000240 ~ DL000248					
22	DB0000000					MB903270
42/48						
	101 Axis (SP) DL000250 ~ DL000258					
23	DB0000000					MB903280
44/48						
	102 Axis (SP) DL000260 ~ DL000268					
24	DB0000000					MB903290
46/50						
	103 Axis (SP) DL000270 ~ DL000278					
25	DB0000000					MB903300
48/52						
	104 Axis (SP) DL000280 ~ DL000288					
26	DB0000000					MB903310
50/54						
	105 Axis (SP) DL000290 ~ DL000298					
27	DB0000000					MB903320
52/56						
	106 Axis (SP) DL00300 ~ DL00308					
28	DB0000000					MB903330
54/58						
	107 Axis (SP) DL00310 ~ DL00318					
29	DB0000000					MB903340
56/60						
	108 Axis (SP) DL00320 ~ DL00328					
30	DB0000000					MB903350
58/62						
	109 Axis (SP) DL00330 ~ DL00338					
31	DB0000000					MB903360
60/64						
	110 Axis (SP) DL00340 ~ DL00348					
32	DB0000000					MB903370
62/68						
	111 Axis (SP) DL00350 ~ DL00358					
33	DB0000000					MB903380
64/68						

