


	L60.25:Step Btn Enable(8 Circuit)								
0 0/0	MB00000F					DB000000	[DB000000] .../0008 .../0014 .../0020 .../0026 .../0032 .../0038 .../0044 .../0050 .../0056 .../0062 .../0068	.../0010 .../0016 .../0022 .../0028 .../0034 .../0040 .../0046 .../0052 .../0058 .../0064 .../0070	.../0012 .../0018 .../0024 .../0030 .../0036 .../0042 .../0048 .../0054 .../0060 .../0066
1 2/2	Debug								
2 3/5					SETW MW90436 ---	[W]Dest MW90436 --- [W>Data HFFFF [W]Width 00016	[MW90436] .../0077w	L40.40/0243i	
					SETW MW90564 ---	[W]Dest MW90564 --- [W>Data HFFFF [W]Width 00016	[MW90564] .../0080w	L40.40/0318i	
	Step(-) Enable 조건 81 Axis (SP) DL00010 ~ DL00018								
3 4/8	DB000000					MB904360	[MB904360] L60.24/0053w		
	82 Axis (SP) DL00020 ~ DL00028								
4 8/10	DB000000					MB904370	[MB904370] L60.24/0055w		
	83 Axis (SP) DL00030 ~ DL00038								
5 8/12	DB000000					MB904380	[MB904380] L60.24/0057w		
	84 Axis (SP) DL00040 ~ DL00048								
6 10/14	DB000000					MB904390	[MB904390] L60.24/0059w		
	85 Axis (SP) DL00050 ~ DL00058								
7 12/16	DB000000					MB904400	[MB904400] L60.24/0061w		
	86 Axis (SP) DL00060 ~ DL00068								
8 14/18	DB000000					MB904410	[MB904410] L60.24/0063w		
	87 Axis (SP) DL00070 ~ DL00078								
9 16/20	DB000000					MB904420	[MB904420] L60.24/0065w		
	88 Axis (SP) DL00080 ~ DL00088								
10 18/22	DB000000					MB904430	[MB904430] L60.24/0067w		
	89 Axis (SP) DL00090 ~ DL00098								
11 20/24	DB000000					MB904440	[MB904440] L60.24/0069w		
	90 Axis (SP) DL000100 ~ DL000108								
12 22/26	DB000000					MB904450	[MB904450] L60.24/0071w		
	91 Axis (SP) DL000110 ~ DL000118								
13 24/28	DB000000					MB904460	[MB904460] L60.24/0073w		
	92 Axis (SP) DL000120 ~ DL000128								
14 26/30	DB000000					MB904470	[MB904470] L60.24/0075w		
	93 Axis (SP) DL000130 ~ DL000138								
15 28/32	DB000000					MB904480	[MB904480] L60.24/0077w		
	94 Axis (SP) DL000140 ~ DL000148								
16 30/34	DB000000					MB904490	[MB904490] L60.24/0079w		
				L60.25 : Step Btn Enable(8 Circuit)				P00001	

	95 Axis (SP) DL000150 ~ DL000158					
17	DB0000000				MB904500	
32/38						
	96 Axis (SP) DL000160 ~ DL000168					
18	DB0000000				MB904510	
34/38						
	Step(+) Enable 조건 81 Axis (SP) DL000210 ~ DL000218					
19	DB0000000				MB905640	
36/40						
	82 Axis (SP) DL000220 ~ DL000228					
20	DB0000000				MB905650	
38/42						
	83 Axis (SP) DL000230 ~ DL000238					
21	DB0000000				MB905660	
40/44						
	84 Axis (SP) DL000240 ~ DL000248					
22	DB0000000				MB905670	
42/46						
	85 Axis (SP) DL000250 ~ DL000258					
23	DB0000000				MB905680	
44/48						
	86 Axis (SP) DL000260 ~ DL000268					
24	DB0000000				MB905690	
46/50						
	87 Axis (SP) DL000270 ~ DL000278					
25	DB0000000				MB905700	
48/52						
	88 Axis (SP) DL000280 ~ DL000288					
26	DB0000000				MB905710	
50/54						
	89 Axis (SP) DL000290 ~ DL000298					
27	DB0000000				MB905720	
52/56						
	90 Axis (SP) DL000300 ~ DL000308					
28	DB0000000				MB905730	
54/58						
	91 Axis (SP) DL000310 ~ DL000318					
29	DB0000000				MB905740	
56/60						
	92 Axis (SP) DL000320 ~ DL000328					
30	DB0000000				MB905750	
58/62						
	93 Axis (SP) DL000330 ~ DL000338					
31	DB0000000				MB905760	
60/64						
	94 Axis (SP) DL000340 ~ DL000348					
32	DB0000000				MB905770	
62/66						
	95 Axis (SP) DL000350 ~ DL000358					
33	DB0000000				MB905780	
64/68						

[MB904500]
L60.24/0081w

[MB904510]
L60.24/0083w



[MW90436]
.../0002w
[MW90564]
.../0005w

L40.40/0243i
L40.40/0318i