

	L60.32:					
0	MB00000F					DB000000
	Debug					---
1				SETW	[W]Dest MW90644 ---	[W]Data HFFFF [W]Width 00016
	ABS Enable 조건 33 Axis (CX) DL00010 ~ DL00018					
2	DB000000					MB906440
	---					---
	34 Axis (CAMX) DL00020 ~ DL00028					
3	DB000000					MB906450
	---					---
	35 Axis (CZ) DL00030 ~ DL00038					
4	DB000000					MB906460
	---					---
	36 Axis (CS) DL00040 ~ DL00048					
5	DB000000					MB906470
	---					---
	37 Axis (SP) DL00050 ~ DL00058					
6	DB000000					MB906480
	---					---
	38 Axis (LCAMY) DL00060 ~ DL00068					
7	DB000000					MB906490
	---					---
	39 Axis (RCAMY) DL00070 ~ DL00078					
8	DB000000					MB906500
	---					---
	40 Axis (LCAMZ) DL00080 ~ DL00088					
9	DB000000					MB906510
	---					---
	41 Axis (RCAMZ) DL00090 ~ DL00098					
10	DB000000					MB906520
	---					---
	42 Axis (SP) DL00100 ~ DL00108					
11	DB000000					MB906530
	---					---
	43 Axis (SP) DL00110 ~ DL00118					
12	DB000000					MB906540
	---					---
	44 Axis (SP) DL00120 ~ DL00128					
13	DB000000					MB906550
	---					---
	45 Axis (SP) DL00130 ~ DL00138					
14	DB000000					MB906560
	---					---
	46 Axis (SP) DL00140 ~ DL00148					
15	DB000000					MB906570
	---					---
	47 Axis (SP) DL00150 ~ DL00158					
16	DB000000					MB906580
	---					---

[DB000000]
.../0005
.../0011
.../0017
.../0023
.../0029
.../0035
[MW90644]
.../0042w

.../0007
.../0013
.../0019
.../0025
.../0031
.../0009
.../0015
.../0021
.../0027
.../0033
L40.41/0028i

