

	L60.33:					
0	MB00000F					DB000000
	Debug					---
1				SETW	[W]Dest MW90660 ---	[W]Data HFFFF [W]Width 00016
	ABS Enable 조건 49 Axis (SCHY1) DL00010 ~ DL00018					
2	DB000000					MB906600
	---					---
	50 Axis (SCHY2) DL00020 ~ DL00028					
3	DB000000					MB906610
	---					---
	51 Axis (SP) DL00030 ~ DL00038					
4	DB000000					MB906620
	---					---
	52 Axis (SCH1Z) DL00040 ~ DL00048					
5	DB000000					MB906630
	---					---
	53 Axis (SCH2Z) DL00050 ~ DL00058					
6	DB000000					MB906640
	---					---
	54 Axis (SCH3Z) DL00060 ~ DL00068					
7	DB000000					MB906650
	---					---
	55 Axis (SCH4Z) DL00070 ~ DL00078					
8	DB000000					MB906660
	---					---
	56 Axis (SCH5Z) DL00080 ~ DL00088					
9	DB000000					MB906670
	---					---
	57 Axis (SCH6Z) DL00090 ~ DL00098					
10	DB000000					MB906680
	---					---
	58 Axis (SCH7Z) DL00100 ~ DL00108					
11	DB000000					MB906690
	---					---
	59 Axis (SCH8Z) DL00110 ~ DL00118					
12	DB000000					MB906700
	---					---
	60 Axis (SP) DL00120 ~ DL00128					
13	DB000000					MB906710
	---					---
	61 Axis (SP) DL00130 ~ DL00138					
14	DB000000					MB906720
	---					---
	62 Axis (SP) DL00140 ~ DL00148					
15	DB000000					MB906730
	---					---
	63 Axis (SP) DL00150 ~ DL00158					
16	DB000000					MB906740
	---					---

[DB000000]
.../0005
.../0011
.../0017
.../0023
.../0029
.../0035
[MW90660]
.../0042w

.../0007
.../0013
.../0019
.../0025
.../0031
.../0009
.../0015
.../0021
.../0027
.../0033
L40.41/0034i

