

	L60.35:ABS Btn Enable (8 Circuit)						
0	MB00000F						DB000000
	Debug						---
1				SETW	[W]Dest MW90692 ---	[W]Data HFFFF	[W]Width 00016
	ABS Enable 조건 81 Axis (SP) DL00010 ~ DL00018						
2	DB000000						MB906920
	---						---
	82 Axis (SP) DL00020 ~ DL00028						
3	DB000000						MB906930
	---						---
	83 Axis (SP) DL00030 ~ DL00038						
4	DB000000						MB906940
	---						---
	84 Axis (SP) DL00040 ~ DL00048						
5	DB000000						MB906950
	---						---
	85 Axis (SP) DL00050 ~ DL00058						
6	DB000000						MB906960
	---						---
	86 Axis (SP) DL00060 ~ DL00068						
7	DB000000						MB906970
	---						---
	87 Axis (SP) DL00070 ~ DL00078						
8	DB000000						MB906980
	---						---
	88 Axis (SP) DL00080 ~ DL00088						
9	DB000000						MB906990
	---						---
	89 Axis (SP) DL00090 ~ DL00098						
10	DB000000						MB907000
	---						---
	90 Axis (SP) DL00100 ~ DL00108						
11	DB000000						MB907010
	---						---
	91 Axis (SP) DL00110 ~ DL00118						
12	DB000000						MB907020
	---						---
	92 Axis (SP) DL00120 ~ DL00128						
13	DB000000						MB907030
	---						---
	93 Axis (SP) DL00130 ~ DL00138						
14	DB000000						MB907040
	---						---
	94 Axis (SP) DL00140 ~ DL00148						
15	DB000000						MB907050
	---						---
	95 Axis (SP) DL00150 ~ DL00158						
16	DB000000						MB907060
	---						---

[DB000000]
.../0005
.../0011
.../0017
.../0023
.../0029
.../0035
[MW90692]
.../0042w

.../0007
.../0013
.../0019
.../0025
.../0031

L40.41/0046i

