

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Scribe SCH Y Auto Task
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 " SCH Y Command Reset
00021 00000 MW04518 = 0;
00022 00001 MB045190 = 0;
00023 00002 MB045191 = 0;
00024
00025 00003 DB00000 = 0;
00026 00004 WHILE DB00000 == 0 " Cycle Stop Chec
00027 " SC SCH Unit Command Code Waiting
00028 00005 IOW MW04518 <> 0;
00029
00030 " Scribe SCH Check
00031 00006 IF MB000004 == 1
00032 00007 IF (MB030034 & MB04512F) | MB030035 == 1;
00033 00008 IF MB09018E | MB000800 == 1 " [Sensor] SCT Scribe SCH All Vacuum On
00034 " [Request] Moving Position
00035 00009 IF CW00099 == 1;
00036 00010 IF !MB04574C == 1;
00037 00011 MW04820 = 40;
00038 00012 MSEE MPS256;
00039 00013 IEND;
00040 00014 ELSE;
00041 00015 MW04820 = 40;
00042 00016 MSEE MPS256;
00043 00017 IEND;
00044 00018 IOW MB04574C == 1 " All SCHZ Moving Pos Check
00045 00019 ELSE;
00046 " [Request] Vacuum Position
00047 00020 MW04820 = 41;
00048 00021 MSEE MPS256;
00049 00022 IOW MB04574B == 1 " All SCHZ Vacuum Pos Check
00050
00051 00023 MB09048E = 1; " [Sol] SCT Scribe SCH All Vacuum On
00052 00024 IOW MB09018E == 1 " [Sensor] SCT Scribe SCH All Vacuum On
00053
00054 " [Request] Moving Position
00055 00025 MW04820 = 40;
00056 00026 MSEE MPS256;
00057 00027 IOW MB04574C == 1 " All SCHZ Moving Pos Check
00058 00028 IEND;
00059 00029 ELSE;
00060 00030 MB09052E = 1; " [Sol] SCT Scribe SCH All Vacuum Off
00061 00031 MB090560 = 1; " [Sol] SCT Scribe SCH 1,2,3,4 Blow On
00062 00032 IOW MB09022E & MB090260 == 1 " [Sensor] SCT Scribe SCH All Vacuum Off
00063 " [Sensor] SCT Scribe SCH 1,2,3,4 Blow On
00064 00033 TIM TMW26214; " Scribe SCH Vacuum Break Complete Timer
00065 00034 MB090600 = 1; " [Sol] SCT Scribe SCH 1,2,3,4 Blow Off
00066 00035 IOW MB090300 == 1 " [Sensor] SCT Scribe SCH 1,2,3,4 Blow Off
00067
00068 " [Request] Standby Position
00069 00036 MW04820 = 39;
00070 00037 MSEE MPS256;
00071 00038 IOW MB04574A == 1 " All SCHZ Standby Pos Check
00072 00039 IEND;
00073 00040 IEND;
00074
00075 " Cutter Z Waiton Position
00076 00041 IF MB045740 | MB045743 == 0;
00077 00042 IF MW04518 <> 2;
00078 00043 IOW MW04842 == 0;
00079 00044 MW04842 = 41;
00080 00045 MSEE MPS198;
00081 //MW04842 = 0;
00082 00046 IOW MW04842 == 0;
00083 00047 IEND;
00084 00048 IEND;
00085
00086 //IOW MB045780 == 0 " Fix Table PIO Permission
00087

```

```

00088      " Scribe SCH 1, 2 Position Compa:
00089 00049  IF IL0A816 <> IL0A896;
00090 00050      MSEE MPS228;
00091 00051  IEND;
00092
00093      " Scribe SCH Y Motion Type Select
00094 00052  SFORK  MW04518 == 1 ? LBL01      "[SCH] Waiting Position
00095      MW04518 == 2 ? LBL02      "[SCH] Receive Position
00096      MW04518 == 3 ? LBL03      "[SCH] Alignment Before Position
00097      MW04518 == 4 ? LBL04      "[SCH] Alignment Position
00098      MW04518 == 5 ? LBL05      "[SCH] Scribe Start Position
00099      MW04518 == 6 ? LBL06      "[SCH] 0 Point Position
00100      MW04518 == 7 ? LBL07      "[SCH] SCH Level Detect Position
00101      MW04518 == 8 ? LBL08      "[SCH] Wheel Align Position
00102      MW04518 == 9 ? LBL09      "[SCH] Before Pitch Alignment Positon
00103      MW04518 == 10 ? LBL10     "[SCH] SCH Task End Process
00104      MW04518 == 11 ? LBL11     "[SCH] Cutter OffsetSet Scribe Positon
00105      MW04518 == 12 ? LBL12     "[SCH] DummyCut LastFeeding Position
00106      MW04518 == 13 ? LBL13     "[SCH] DummyCut Alignment Position
00107      MW04518 == 14 ? LBL14     "[SCH] Break Position
00108      MW04518 == 15 ? LBL15     "[SCH] Lower Safety Position 1 Cycle
00109      DEFAULT ? LBL100;
00110
00111 00053  LBL01:
00112      " [SC Response SCH] Auto Complet
00113 00054      IOW MB045190 == 1;
00114 00055      IOW MB045780 == 0      " Fix Table PIO Permission
00115
00116 00056      MSEE MPS221;      "[SCH] Waiting Position 1 Cycle
00117
00118 00057      MB045191 = 1;      " SC Response Scribe SCH Command Complete Bit
00119      On
00120
00120      " Last Scribe Pitch Check
00121 00058  IF GL21158 <= MW15411;
00122 00059      MB045190 = 0;
00123 00060      TIM T100;
00124 00061  IEND;
00125
00126 00062      IOW MB045190 == 0      " SC Request Scribe SCH Command Execute Bit
00127      On
00127 00063      MB045191 = 0;      " SC Response Scribe SCH Command Complete Bit
00128      On
00128 00064      MW04518 = 0;      " SC Request Scribe SCH Command Code Setting
00129
00130 00065      JOINTO LBL0X;
00131
00132 00066  LBL02:
00133      " [SC Response SCH] Auto Complet
00134 00067      IOW MB045190 == 1;
00135 00068      IOW MB045780 == 0      " Fix Table PIO Permission
00136 00069      MSEE MPS222;      "[SCH] Receive Position 1 Cycle
00137
00138 00070      MB045191 = 1;      " SC Response Scribe SCH Command Complete Bit
00139      On
00140
00140      " Last Scribe Pitch Check
00141 00071  IF GL21158 <= MW15411;
00142 00072      MB045190 = 0;
00143 00073      TIM T100;
00144 00074  IEND;
00145
00146 00075      IOW MB045190 == 0      " SC Request Scribe SCH Command Execute Bit
00147      On
00147 00076      MB045191 = 0;      " SC Response Scribe SCH Command Complete Bit
00148      On
00148 00077      MW04518 = 0;      " SC Request Scribe SCH Command Code Setting
00149
00150      //      IF MW04510 <> 2      " Glass Receive 1 Cycle
00151      //      IF (!MB030034 & !MB030035) & MB002002 & !MB04570F == 1;
00152      //      IF MB053100 & MB000004 & !MB045013 == 1;
00153      //      IF MW04018 == 5      " MTR Auto #5 ( MTR Carry Out PIO
00154      //      MSEE MPS234;      " MTR ↔ SC Interface
00155      //
00156      //      DB000110 = 0;
00157      //      WHILE DB000110 == 0
00158      //          IF MB04513A == 1      "[Last Break] Breaking Execute Pos. Comp
00159      //              MSEE MPS235;      "[SCH] ScribeFeed Alignment Position
00160      //              DB000110 = 1;
00161      //          IEND;
00162      //          IF MB045013 == 1;
00163      //              DB000110 = 1;
00164      //          IEND;
00165      //          IF MB030035 == 1;
00166      //              DB000110 = 1;
00167      //          IEND;

```

```

00168      //                      EOX;
00169      //                      WEND;
00170      //
00171      //                      IOW MW04513 == 0
00172      //                      IEND;
00173      //                      IEND;
00174      //                      IEND;
00175      //                      IEND;
00176
00177 00078      JOINTO LBL0X;
00178
00179 00079      LBL03:
00180      " [SC Response SCH] Auto Complet
00181 00080      IOW MB045190 == 1;
00182
00183 00081      MSEE MPS223;
00184      " [SCH] Alignment Before Position 1 Cycle
00185 00082      MB045191 = 1;
00186 00083      IOW MB045190 == 0
00187 00084      MB045191 = 0;
00188 00085      " SC Response Scribe SCH Command Complete Bit On
00189      " SC Request Scribe SCH Command Execute Bit On
00190 00086      MW04518 = 0;
00191      " SC Response Scribe SCH Command Complete Bit
00192 00087      " SC Request Scribe SCH Command Code Setting
00193      JOINTO LBL0X;
00194
00195 00088      LBL04:
00196      " [SC Response SCH] Auto Complet
00197      IOW MB045190 == 1;
00198
00199 00089      MSEE MPS224;
00200      " [SCH] Alignment Position 1 Cycle
00201 00090      MB045191 = 1;
00202 00091      IOW MB045190 == 0
00203 00092      MB045191 = 0;
00204 00093      " SC Response Scribe SCH Command Complete Bit On
00205 00094      " SC Request Scribe SCH Command Execute Bit On
00206 00095      MW04518 = 0;
00207 00096      " SC Response Scribe SCH Command Complete Bit
00208      " SC Request Scribe SCH Command Code Setting
00209 00097      JOINTO LBL0X;
00210
00211 00098      LBL05:
00212 00099      " [SC Response SCH] Auto Complet
00213 00100      IOW MB045190 == 1;
00214
00215 00101      MSEE MPS225;
00216 00102      " [SCH] Scribe Start Position 1 Cycle
00217 00103      MB045191 = 1;
00218 00104      IOW MB045190 == 0
00219 00105      MB045191 = 0;
00220 00106      " SC Response Scribe SCH Command Complete Bit On
00221 00107      " SC Request Scribe SCH Command Execute Bit On
00222 00108      MW04518 = 0;
00223 00109      " SC Response Scribe SCH Command Complete Bit
00224      " SC Request Scribe SCH Command Code Setting
00225 00110      JOINTO LBL0X;
00226
00227 00111      LBL06:
00228 00112      " [SC Response SCH] Auto Complet
00229 00113      IOW MB045190 == 1;
00230
00231 00114      MSEE MPS226;
00232 00115      " [SCH] Scribe 0 Point Position 1 Cycle
00233 00116      MB045191 = 1;
00234 00117      IOW MB045190 == 0
00235 00118      MB045191 = 0;
00236 00119      " SC Response Scribe SCH Command Complete Bit On
00237 00120      " SC Request Scribe SCH Command Execute Bit On
00238 00121      MW04518 = 0;
00239 00122      " SC Response Scribe SCH Command Complete Bit
00240 00123      " SC Request Scribe SCH Command Code Setti
00241 00124      JOINTO LBL0X;
00242
00243 00125      LBL07:
00244 00126      " [SC Response SCH] Auto Complet
00245 00127      IOW MB045190 == 1;
00246
00247 00128      MSEE MPS227;
00248 00129      " [SCH] Scribe SCH Level Measurement Position
00249 00130      MB045191 = 1;
00250 00131      IOW MB045190 == 0
00251 00132      MB045191 = 0;
00252 00133      " SC Response Scribe SCH Command Complete Bit On
00253 00134      " SC Request Scribe SCH Command Execute Bit On
00254 00135      MW04518 = 0;
00255 00136      " SC Response Scribe SCH Command Complete Bit
00256 00137      " SC Request Scribe SCH Command Code Setti
00257 00138      JOINTO LBL0X;
00258
00259 00139      LBL08:
00260 00140      " [SC Response SCH] Auto Complet
00261 00141      IOW MB045190 == 1;
00262 00142
00263 00143      MSEE MPS228;
00264 00144      " [SCH] Scribe SCH Level Measurement Position
00265 00145      MB045191 = 1;
00266 00146      IOW MB045190 == 0
00267 00147      MB045191 = 0;
00268 00148      " SC Response Scribe SCH Command Complete Bit On
00269 00149      " SC Request Scribe SCH Command Execute Bit On
00270 00150      MW04518 = 0;
00271 00151      " SC Response Scribe SCH Command Complete Bit
00272 00152      " SC Request Scribe SCH Command Code Setti
00273 00153      JOINTO LBL0X;
00274
00275 00154      LBL09:
00276 00155      " [SC Response SCH] Auto Complet
00277 00156      IOW MB045190 == 1;
00278
00279 00157      MSEE MPS229;
00280 00158      " [SCH] Scribe SCH Level Measurement Position
00281 00159      MB045191 = 1;
00282 00160      IOW MB045190 == 0
00283 00161      MB045191 = 0;
00284 00162      " SC Response Scribe SCH Command Complete Bit On
00285 00163      " SC Request Scribe SCH Command Execute Bit On
00286 00164      MW04518 = 0;
00287 00165      " SC Response Scribe SCH Command Complete Bit
00288 00166      " SC Request Scribe SCH Command Code Setti
00289 00167      JOINTO LBL0X;
00290
00291 00168      LBL10:
00292 00169      " [SC Response SCH] Auto Complet
00293 00170      IOW MB045190 == 1;
00294
00295 00171      MSEE MPS230;
00296 00172      " [SCH] Scribe SCH Level Measurement Position
00297 00173      MB045191 = 1;
00298 00174      IOW MB045190 == 0
00299 00175      MB045191 = 0;
00300 00176      " SC Response Scribe SCH Command Complete Bit On
00301 00177      " SC Request Scribe SCH Command Execute Bit On
00302 00178      MW04518 = 0;
00303 00179      " SC Response Scribe SCH Command Complete Bit
00304 00180      " SC Request Scribe SCH Command Code Setti
00305 00181      JOINTO LBL0X;
00306
00307 00182      LBL11:
00308 00183      " [SC Response SCH] Auto Complet
00309 00184      IOW MB045190 == 1;
00310
00311 00185      MSEE MPS231;
00312 00186      " [SCH] Scribe SCH Level Measurement Position
00313 00187      MB045191 = 1;
00314 00188      IOW MB045190 == 0
00315 00189      MB045191 = 0;
00316 00190      " SC Response Scribe SCH Command Complete Bit On
00317 00191      " SC Request Scribe SCH Command Execute Bit On
00318 00192      MW04518 = 0;
00319 00193      " SC Response Scribe SCH Command Complete Bit
00320 00194      " SC Request Scribe SCH Command Code Setti
00321 00195      JOINTO LBL0X;
00322
00323 00196      LBL12:
00324 00197      " [SC Response SCH] Auto Complet
00325 00198      IOW MB045190 == 1;
00326
00327 00199      MSEE MPS232;
00328 00200      " [SCH] Scribe SCH Level Measurement Position
00329 00201      MB045191 = 1;
00330 00202      IOW MB045190 == 0
00331 00203      MB045191 = 0;
00332 00204      " SC Response Scribe SCH Command Complete Bit On
00333 00205      " SC Request Scribe SCH Command Execute Bit On
00334 00206      MW04518 = 0;
00335 00207      " SC Response Scribe SCH Command Complete Bit
00336 00208      " SC Request Scribe SCH Command Code Setti
00337 00209      JOINTO LBL0X;
00338
00339 00210      LBL13:
00340 00211      " [SC Response SCH] Auto Complet
00341 00212      IOW MB045190 == 1;
00342
00343 00213      MSEE MPS233;
00344 00214      " [SCH] Scribe SCH Level Measurement Position
00345 00215      MB045191 = 1;
00346 00216      IOW MB045190 == 0
00347 00217      MB045191 = 0;
00348 00218      " SC Response Scribe SCH Command Complete Bit On
00349 00219      " SC Request Scribe SCH Command Execute Bit On
00350 00220      MW04518 = 0;
00351 00221      " SC Response Scribe SCH Command Complete Bit
00352 00222      " SC Request Scribe SCH Command Code Setti
00353 00223      JOINTO LBL0X;
00354
00355 00224      LBL14:
00356 00225      " [SC Response SCH] Auto Complet
00357 00226      IOW MB045190 == 1;
00358
00359 00227      MSEE MPS234;
00360 00228      " [SCH] Scribe SCH Level Measurement Position
00361 00229      MB045191 = 1;
00362 00230      IOW MB045190 == 0
00363 00231      MB045191 = 0;
00364 00232      " SC Response Scribe SCH Command Complete Bit On
00365 00233      " SC Request Scribe SCH Command Execute Bit On
00366 00234      MW04518 = 0;
00367 00235      " SC Response Scribe SCH Command Complete Bit
00368 00236      " SC Request Scribe SCH Command Code Setti
00369 00237      JOINTO LBL0X;
00370
00371 00238      LBL15:
00372 00239      " [SC Response SCH] Auto Complet
00373 00240      IOW MB045190 == 1;
00374
00375 00241      MSEE MPS235;
00376 00242      " [SCH] Scribe SCH Level Measurement Position
00377 00243      MB045191 = 1;
00378 00244      IOW MB045190 == 0
00379 00245      MB045191 = 0;
00380 00246      " SC Response Scribe SCH Command Complete Bit On
00381 00247      " SC Request Scribe SCH Command Execute Bit On
00382 00248      MW04518 = 0;
00383 00249      " SC Response Scribe SCH Command Complete Bit
00384 00250      " SC Request Scribe SCH Command Code Setti
00385 00251      JOINTO LBL0X;
00386
00387 00252      LBL16:
00388 00253      " [SC Response SCH] Auto Complet
00389 00254      IOW MB045190 == 1;
00390
00391 00255      MSEE MPS236;
00392 00256      " [SCH] Scribe SCH Level Measurement Position
00393 00257      MB045191 = 1;
00394 00258      IOW MB045190 == 0
00395 00259      MB045191 = 0;
00396 00260      " SC Response Scribe SCH Command Complete Bit On
00397 00261      " SC Request Scribe SCH Command Execute Bit On
00398 00262      MW04518 = 0;
00399 00263      " SC Response Scribe SCH Command Complete Bit
00400 00264      " SC Request Scribe SCH Command Code Setti
00401 00265      JOINTO LBL0X;
00402
00403 00266      LBL17:
00404 00267      " [SC Response SCH] Auto Complet
00405 00268      IOW MB045190 == 1;
00406
00407 00269      MSEE MPS237;
00408 00270      " [SCH] Scribe SCH Level Measurement Position
00409 00271      MB045191 = 1;
00410 00272      IOW MB045190 == 0
00411 00273      MB045191 = 0;
00412 00274      " SC Response Scribe SCH Command Complete Bit On
00413 00275      " SC Request Scribe SCH Command Execute Bit On
00414 00276      MW04518 = 0;
00415 00277      " SC Response Scribe SCH Command Complete Bit
00416 00278      " SC Request Scribe SCH Command Code Setti
00417 00279      JOINTO LBL0X;
00418
00419 00280      LBL18:
00420 00281      " [SC Response SCH] Auto Complet
00421 00282      IOW MB045190 == 1;
00422
00423 00283      MSEE MPS238;
00424 00284      " [SCH] Scribe SCH Level Measurement Position
00425 00285      MB045191 = 1;
00426 00286      IOW MB045190 == 0
00427 00287      MB045191 = 0;
00428 00288      " SC Response Scribe SCH Command Complete Bit On
00429 00289      " SC Request Scribe SCH Command Execute Bit On
00430 00290      MW04518 = 0;
00431 00291      " SC Response Scribe SCH Command Complete Bit
00432 00292      " SC Request Scribe SCH Command Code Setti
00433 00293      JOINTO LBL0X;
00434
00435 00294      LBL19:
00436 00295      " [SC Response SCH] Auto Complet
00437 00296      IOW MB045190 == 1;
00438
00439 00297      MSEE MPS239;
00440 00298      " [SCH] Scribe SCH Level Measurement Position
00441 00299      MB045191 = 1;
00442 00300      IOW MB045190 == 0
00443 00301      MB045191 = 0;
00444 00302      " SC Response Scribe SCH Command Complete Bit On
00445 00303      " SC Request Scribe SCH Command Execute Bit On
00446 00304      MW04518 = 0;
00447 00305      " SC Response Scribe SCH Command Complete Bit
00448 00306      " SC Request Scribe SCH Command Code Setti
00449 00307      JOINTO LBL0X;
00450
00451 00308      LBL20:
00452 00309      " [SC Response SCH] Auto Complet
00453 00310      IOW MB045190 == 1;
00454
00455 00311      MSEE MPS240;
00456 00312      " [SCH] Scribe SCH Level Measurement Position
00457 00313      MB045191 = 1;
00458 00314      IOW MB045190 == 0
00459 00315      MB045191 = 0;
00460 00316      " SC Response Scribe SCH Command Complete Bit On
00461 00317      " SC Request Scribe SCH Command Execute Bit On
00462 00318      MW04518 = 0;
00463 00319      " SC Response Scribe SCH Command Complete Bit
00464 00320      " SC Request Scribe SCH Command Code Setti
00465 00321      JOINTO LBL0X;
00466
00467 00322      LBL21:
00468 00323      " [SC Response SCH] Auto Complet
00469 00324      IOW MB045190 == 1;
00470
00471 00325      MSEE MPS241;
00472 00326      " [SCH] Scribe SCH Level Measurement Position
00473 00327      MB045191 = 1;
00474 00328      IOW MB045190 == 0
00475 00329      MB045191 = 0;
00476 00330      " SC Response Scribe SCH Command Complete Bit On
00477 00331      " SC Request Scribe SCH Command Execute Bit On
00478 00332      MW04518 = 0;
00479 00333      " SC Response Scribe SCH Command Complete Bit
00480 00334      " SC Request Scribe SCH Command Code Setti
00481 00335      JOINTO LBL0X;
00482
00483 00336      LBL22:
00484 00337      " [SC Response SCH] Auto Complet
00485 00338      IOW MB045190 == 1;
00486
00487 00339      MSEE MPS242;
00488 00340      " [SCH] Scribe SCH Level Measurement Position
00489 00341      MB045191 = 1;
00490 00342      IOW MB045190 == 0
00491 00343      MB045191 = 0;
00492 00344      " SC Response Scribe SCH Command Complete Bit On
00493 00345      " SC Request Scribe SCH Command Execute Bit On
00494 00346      MW04518 = 0;
00495 00347      " SC Response Scribe SCH Command Complete Bit
00496 00348      " SC Request Scribe SCH Command Code Setti
00497 00349      JOINTO LBL0X;
00498
00499 00350      LBL23:
00500 00351      " [SC Response SCH] Auto Complet
00501 00352      IOW MB045190 == 1;
00502
00503 00353      MSEE MPS243;
00504 00354      " [SCH] Scribe SCH Level Measurement Position
00505 00355      MB045191 = 1;
00506 00356      IOW MB045190 == 0
00507 00357      MB045191 = 0;
00508 00358      " SC Response Scribe SCH Command Complete Bit On
00509 00359      " SC Request Scribe SCH Command Execute Bit On
00510 00360      MW04518 = 0;
00511 00361      " SC Response Scribe SCH Command Complete Bit
00512 00362      " SC Request Scribe SCH Command Code Setti
00513 00363      JOINTO LBL0X;
00514
00515 00364      LBL24:
00516 00365      " [SC Response SCH] Auto Complet
00517 00366      IOW MB045190 == 1;
00518
00519 00367      MSEE MPS244;
00520 00368      " [SCH] Scribe SCH Level Measurement Position
00521 00369      MB045191 = 1;
00522 00370      IOW MB045190 == 0
00523 00371      MB045191 = 0;
00524 00372      " SC Response Scribe SCH Command Complete Bit On
00525 00373      " SC Request Scribe SCH Command Execute Bit On
00526 00374      MW04518 = 0;
00527 00375      " SC Response Scribe SCH Command Complete Bit
00528 00376      " SC Request Scribe SCH Command Code Setti
00529 00377      JOINTO LBL0X;
00530
00531 00378      LBL25:
00532 00379      " [SC Response SCH] Auto Complet
00533 00380      IOW MB045190 == 1;
00534
00535 00381      MSEE MPS245;
00536 00382      " [SCH] Scribe SCH Level Measurement Position
00537 00383      MB045191 = 1;
00538 00384      IOW MB045190 == 0
00539 00385      MB045191 = 0;
00540 00386      " SC Response Scribe SCH Command Complete Bit On
00541 00387      " SC Request Scribe SCH Command Execute Bit On
00542 00388      MW04518 = 0;
00543 00389      " SC Response Scribe SCH Command Complete Bit
00544 00390      " SC Request Scribe SCH Command Code Setti
00545 00391      JOINTO LBL0X;
00546
00547 00392      LBL26:
00548 00393      " [SC Response SCH] Auto Complet
00549 00394      IOW MB045190 == 1;
00550
00551 00395      MSEE MPS246;
00552 00396      " [SCH] Scribe SCH Level Measurement Position
00553 00397      MB045191 = 1;
00554 00398      IOW MB045190 == 0
00555 00399      MB045191 = 0;
00556 00400      " SC Response Scribe SCH Command Complete Bit On
00557 00401      " SC Request Scribe SCH Command Execute Bit On
00558 00402      MW04518 = 0;
00559 00403      " SC Response Scribe SCH Command Complete Bit
00560 00404      " SC Request Scribe SCH Command Code Setti
00561 00405      JOINTO LBL0X;
00562
00563 00406      LBL27:
00564 00407      " [SC Response SCH] Auto Complet
00565 00408      IOW MB045190 == 1;
00566
00567 00409      MSEE MPS247;
00568 00410      " [SCH] Scribe SCH Level Measurement Position
00569 00411      MB045191 = 1;
00570 00412      IOW MB045190 == 0
00571 00413      MB045191 = 0;
00572 00414      " SC Response Scribe SCH Command Complete Bit On
00573 00415      " SC Request Scribe SCH Command Execute Bit On
00574 00416      MW04518 = 0;
00575 00417      " SC Response Scribe SCH Command Complete Bit
00576 00418      " SC Request Scribe SCH Command Code Setti
00577 00419      JOINTO LBL0X;
00578
00579 00420      LBL28:
00580 00421      " [SC Response SCH] Auto Complet
00581 00422      IOW MB045190 == 1;
00582
00583 00423      MSEE MPS248;
00584 00424      " [SCH] Scribe SCH Level Measurement Position
00585 00425      MB045191 = 1;
00586 00426      IOW MB045190 == 0
00587 00427      MB045191 = 0;
00588 00428      " SC Response Scribe SCH Command Complete Bit On
00589 00429      " SC Request Scribe SCH Command Execute Bit On
00590 00430      MW04518 = 0;
00591 00431      " SC Response Scribe SCH Command Complete Bit
00592 00432      " SC Request Scribe SCH Command Code Setti
00593 00433      JOINTO LBL0X;
00594
00595 00434      LBL29:
00596 00435      " [SC Response SCH] Auto Complet
00597 00436      IOW MB045190 == 1;
00598
00599 00437      MSEE MPS249;
00600 00438      " [SCH] Scribe SCH Level Measurement Position
00601 00439      MB045191 = 1;
00602 00440      IOW MB045190 == 0
00603 00441      MB045191 = 0;
00604 00442      " SC Response Scribe SCH Command Complete Bit On
00605 00443      " SC Request Scribe SCH Command Execute Bit On
00606 00444      MW04518 = 0;
00607 00445      " SC Response Scribe SCH Command Complete Bit
00608 00446      " SC Request Scribe SCH Command Code Setti
00609 00447      JOINTO LBL0X;
00610
00611 00448      LBL30:
00612 00449      " [SC Response SCH] Auto Complet
00613 00450      IOW MB045190 == 1;
00614
00615 00451      MSEE MPS250;
00616 00452      " [SCH] Scribe SCH Level Measurement Position
00617 00453      MB045191 = 1;
00618 00454      IOW MB045190 == 0
00619 00455      MB045191 = 0;
00620 00456      " SC Response Scribe SCH Command Complete Bit On
00621 00457      " SC Request Scribe SCH Command Execute Bit On
00622 00458      MW04518 = 0;
00623 00459      " SC Response Scribe SCH Command Complete Bit
00624 00460      " SC Request Scribe SCH Command Code Setti
00625 00461      JOINTO LBL0X;
00626
00627 00462      LBL31:
00628 00463      " [SC Response SCH] Auto Complet
00629 00464      IOW MB045190 == 1;
00630
00631 00465      MSEE MPS251;
00632 00466      " [SCH] Scribe SCH Level Measurement Position
00633 00467      MB045191 = 1;
00634 00468      IOW MB045190 == 0
00635 00469      MB045191 = 0;
00636 00470      " SC Response Scribe SCH Command Complete Bit On
00637 00471      " SC Request Scribe SCH Command Execute Bit On
00638 00472      MW04518 = 0;
00639 00473      " SC Response Scribe SCH Command Complete Bit
00640 00474      " SC Request Scribe SCH Command Code Setti
00641 00475      JOINTO LBL0X;
00642
00643 00476      LBL32:
00644 00477      " [SC Response SCH] Auto Complet
00645 00478      IOW MB045190 == 1;
00646
00647 00479      MSEE MPS252;
00648 00480      " [SCH] Scribe SCH Level Measurement Position
00649 00481      MB045191 = 1;
00650 00482      IOW MB045190 == 0
00651 00483      MB045191 = 0;
00652 00484      " SC Response Scribe SCH Command Complete Bit On
00653 00485      " SC Request Scribe SCH Command Execute Bit On
00654 00486      MW04518 = 0;
00655 00487      " SC Response Scribe SCH Command Complete Bit
00656 00488      " SC Request Scribe SCH Command Code Setti
00657 00489      JOINTO LBL0X;
00658
00659 00490      LBL33:
00660 00491      " [SC Response SCH] Auto Complet
00661 00492      IOW MB045190 == 1;
00662
00663 00493      MSEE MPS253;
00664 00494      " [SCH] Scribe SCH Level Measurement Position
00665 00495      MB045191 = 1;
00666 00496      IOW MB045190 == 0
00667 00497      MB045191 = 0;
00668 00498      " SC Response Scribe SCH Command Complete Bit On
00669 00499      " SC Request Scribe SCH Command Execute Bit On
00670 00500      MW04518 = 0;
00671 00501      " SC Response Scribe SCH Command Complete Bit
00672 00502      " SC Request Scribe SCH Command Code Setti
00673 00503      JOINTO LBL0X;
00674
00675 00504      LBL34:
00676 00505      " [SC Response SCH] Auto Complet
00677 00506      IOW MB045190 == 1;
00678
00679 00507      MSEE MPS254;
00680 00508      " [SCH] Scribe SCH Level Measurement Position
00681 00509      MB045191 = 1;
00682 00510      IOW MB045190 == 0
00683 00511      MB045191 = 0;
00684 00512      " SC Response Scribe SCH Command Complete Bit On
00685 00513      " SC Request Scribe SCH Command Execute Bit On
00686 00514      MW04518 = 0;
00687 00515      " SC Response Scribe SCH Command Complete Bit
00688 00516      " SC Request Scribe SCH Command Code Setti
00689 00517      JOINTO LBL0X;
00690
00691 00518      LBL35:
00692 00519      " [SC Response SCH] Auto Complet
00693 00520      IOW MB045190 == 1;
00694
00695 00521      MSEE MPS255;
00696 00522      " [SCH] Scribe SCH Level Measurement Position
00697 00523      MB045191 = 1;
00698 00524      IOW MB045190 == 0
00699 00525      MB045191 = 0;
00700 00526      " SC Response Scribe SCH Command Complete Bit On
00701 00527      " SC Request Scribe SCH Command Execute Bit On
00702 00528      MW04518 = 0;
00703 00529      " SC Response Scribe SCH Command Complete Bit
00704 00530      " SC Request Scribe SCH Command Code Setti
00705 00531      JOINTO LBL0X;
00706
00707 00532      LBL36:
00708 00533      " [SC Response SCH] Auto Complet
00709 00534      IOW MB045190 == 1;
00710
00711 00535      MSEE MPS256;
00712 00536      " [SCH] Scribe SCH Level Measurement Position
00713 00537      MB045191 = 1;
00714 00538      IOW MB045190 == 0
00715 00539      MB045191 = 0;
00716 00540      " SC Response Scribe SCH Command Complete Bit On
00717 00541      " SC Request Scribe SCH Command Execute Bit On
00718 00542      MW04518 = 0;
00719 00543      " SC Response Scribe SCH Command Complete Bit
00720 00544      " SC Request Scribe SCH Command Code Setti
00721 00545      JOINTO LBL0X;
00722
00723 00546      LBL37:
00724 00547      " [SC Response SCH] Auto Complet
00725 00548      IOW MB045190 == 1;
00726
00727 00549      MSEE MPS257;
00728 00550      " [SCH] Scribe SCH Level Measurement Position
00729 00551      MB045191 = 1;
00730 00552      IOW MB045190 == 0
00731 00553      MB045191 = 0;
00732 00554      " SC Response Scribe SCH Command Complete Bit On
00733 00555      " SC Request Scribe SCH Command Execute Bit On
00734 00556      MW04518 = 0;
00735 00557      " SC Response Scribe SCH Command Complete Bit
00736 00558      " SC Request Scribe SCH Command Code Setti
00737 00559      JOINTO LBL0X;
00738
00739 00560      LBL38:
00740 00561      " [SC Response SCH] Auto Complet
00741 00562      IOW MB045190 == 1;
00742
00743 00563      MSEE MPS258;
00744 00564      " [SCH] Scribe SCH Level Measurement Position
00745 00565      MB045191 = 1;
00746 00566      IOW MB045190 == 0
00747 00567      MB045191 = 0;
00748 00568      " SC Response Scribe SCH Command Complete Bit On
00749 00569      " SC Request Scribe SCH Command Execute Bit On
00750 00570      MW04518 = 0;
00751 00571      " SC Response Scribe SCH Command Complete Bit
00752 00572      " SC Request Scribe SCH Command Code Setti
00753 00573      JOINTO LBL0X;
00754
00755 00574      LBL39:
00756 00575      " [SC Response SCH] Auto Complet
00757 00576      IOW MB045190 == 1;
00758
00759 00577      MSEE MPS259;
00760 00578      " [SCH] Scribe SCH Level Measurement Position
00761 00579      MB045191 = 1;
00762 00580      IOW MB045190 == 0
00763 00581      MB045191 = 0;
00764 00582      " SC Response Scribe SCH Command Complete Bit On
00765 00583      " SC Request Scribe SCH Command Execute Bit On
00766 00584      MW04518 = 0;
00767 00585      " SC Response Scribe SCH Command Complete Bit
00768 00586      " SC Request Scribe SCH Command Code Setti
00769 00587      JOINTO LBL0X;
00770
00771 00588      LBL40:
00772 00589      " [SC Response SCH] Auto Complet
00773 00590      IOW MB045190 == 1;
00774
00775 00591      MSEE MPS260;
007
```

```

00248 00121      IOW MB000845 == 1;
00249 00122      MSEE MPS220;
00250
00251 00123      MB045191 = 1;
00252 00124      IOW MB045190 == 0
00253 00125      MB045191 = 0;

00254 00126      MW04518 = 0;

00255
00256 00127      JOINTO LBL0X;
00257
00258 00128      LBL09:
00259      " [SC Response SCH] Auto Complet
00260 00129      IOW MB045190 == 1;
00261
00262 00130      MSEE MPS229;
00263
00264 00131      MB045191 = 1;
00265 00132      IOW MB045190 == 0
00266 00133      MB045191 = 0;

00267 00134      MW04518 = 0;

00268
00269 00135      JOINTO LBL0X;
00270
00271 00136      LBL10:
00272      " SCH Y Task End Command Se
00273      " SCH Y Task Code Reset
00274 00137      MW04518 = 0;
00275      " [SC Response SCH] Auto Complete
00276 00138      MB045190 = 0;
00277 00139      MB045191 = 0;
00278
00279 00140      JOINTO LBL0X;
00280
00281 00141      LBL11:
00282      " [SC Response SCH] Auto Complet
00283 00142      IOW MB045190 == 1;
00284
00285 00143      MSEE MPS219;
00286
00287 00144      MB045191 = 1;
00288 00145      IOW MB045190 == 0
00289 00146      MB045191 = 0;

00290 00147      MW04518 = 0;

00291
00292 00148      JOINTO LBL0X;
00293
00294 00149      LBL12:
00295      " [SC Response SCH] Auto Complet
00296 00150      IOW MB045190 == 1;
00297
00298 00151      MSEE MPS218;
00299
00300 00152      MB045191 = 1;
00301 00153      IOW MB045190 == 0
00302 00154      MB045191 = 0;

00303 00155      MW04518 = 0;

00304
00305 00156      JOINTO LBL0X;
00306
00307 00157      LBL13:
00308      " [SC Response SCH] Auto Complet
00309 00158      IOW MB045190 == 1;
00310
00311 00159      MSEE MPS224;
00312
00313 00160      MB045191 = 1;
00314 00161      IOW MB045190 == 0
00315 00162      MB045191 = 0;

00316 00163      MW04518 = 0;

00317
00318 00164      JOINTO LBL0X;
00319
00320 00165      LBL14:
00321      " [SC Response SCH] Auto Complet
00322 00166      IOW MB045190 == 1;
00323
00324 00167      MSEE MPS236;
00325
00326 00168      MB045191 = 1;
00327 00169      IOW MB045190 == 0
00328 00170      MB045191 = 0;

```

```

" [SCH] Scribe SCH Wheel Align Position

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

" SC Request Scribe SCH Command Code Setting

" [SCH] Before Pitch Alignment Positon

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

" SC Request Scribe SCH Command Code Setti

" [SCH] Cutter OffsetSet Positon

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

" SC Request Scribe SCH Command Code Setting

" [SCH] DummyCut LastFeeding Position

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

" SC Request Scribe SCH Command Code Setting

" [SCH] Alignment Position 1 Cycle

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

" SC Request Scribe SCH Command Code Setting

" [SCH] Pusher Break Position 1 Cycle

" SC Response Scribe SCH Command Complete Bit On
" SC Request Scribe SCH Command Execute Bit On
" SC Response Scribe SCH Command Complete Bit

```

```

00329 00171      MW04518 = 0;                " SC Request Scribe SCH Command Code Setting
00330
00331 00172      JOINTO LBL0X;
00332
00333 00173      LBL15:
00334      " [SC Response SCH] Auto Complet
00335 00174      IOW MB045190 == 1;
00336
00337 00175      MSEE MPS239;                " [SCH] Lower Safety Position 1 Cycle
00338
00339 00176      MB045191 = 1;                " SC Response Scribe SCH Command Complete Bit On
00340 00177      IOW MB045190 == 0                " SC Request Scribe SCH Command Execute Bit On
00341 00178      MB045191 = 0;                " SC Response Scribe SCH Command Complete Bit

00342 00179      MW04518 = 0;                " SC Request Scribe SCH Command Code Setting
00343 00180      JOINTO LBL0X;
00344
00345 00181      LBL100:
00346 00182      JOINTO LBL0X;
00347 00183      LBL0X: SJOINT;
00348
00349      " Scribe SCH Y Motion Type Select
00350 00184      SFORK MW04518 == 16 ? LBL16:    "[SCH] Fix Table Brush Position
00351      DEFAULT ? LBL200;
00352
00353 00185      LBL16:
00354      " [SC Response SCH] Auto Complet
00355 00186      IOW MB045190 == 1;
00356
00357 00187      MSEE MPS242;                " [Chuck] Table Brush Positon
00358
00359 00188      MB045191 = 1;                " SC Response Scribe SCH Command Complete Bit On
00360 00189      IOW MB045190 == 0                " SC Request Scribe SCH Command Execute Bit On
00361 00190      MB045191 = 0;                " SC Response Scribe SCH Command Complete Bit

00362 00191      MW04518 = 0;                " SC Request Scribe SCH Command Code Setting
00363
00364 00192      JOINTO LBL1X;
00365 00193      LBL200:
00366 00194      JOINTO LBL1X;
00367 00195      LBL1X: SJOINT;
00368
00369 00196      IF MB030035 == 1;
00370 00197      IF GL21208 == 1                " Scribe Chuck Z Always Moving Position Mode
00371 00198      IF ML26284 < ILA816;
00372 00199      MW04820 = 41;
00373 00200      MSEE MPS256;
00374 00201      IEND;
00375 00202      ELSE;
00376 00203      MW04820 = 41;
00377 00204      MSEE MPS256;
00378 00205      IEND;
00379 00206      IEND;
00380
00381      " Scribe Stop Request & [ SC BCHK, TBL] Break Stop Request
00382 00207      IF MB045013 & MB045709 == 1;
00383 00208      DB00000 = 1;
00384 00209      IEND;
00385 00210      EOX;
00386 00211      WEND;
00387
00388 00212      END;

```