

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : BKT Home
00011 "# Functior :
00012 "# Call Program : H70.1
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 " Parameter & Interlock
00021 " Scribe Recipe Data Updata Waiting
00022 00000 IOW MB045241 == 1;
00023
00024 " Break Table Parameter Update Waiting
00025 00001 IOW MB55720 == 1;
00026
00027 00002 IOW MB076010 | MB07601A == 1 " Stick Transfer1 Z Stan
dby Pos
00028
00029 " Scribe Unit Home Complete Waiting
00030 00003 IOW MB045240 == 1 " Scribe Home Return Complete
00031
00032 " Break Table Unit Ready
00033 00004 MB05571F = 0;
00034
00035 " Cylinder
00036 " Glass Data Check
00037 00005 IF MB030036 & MB055721 == 1 " Break Break Glass Data Check
00038
00039 00006 ELSE;
00040 00007 IF !MB04524A == 1;
00041 00008 IF MB076011 & MB076001 & !MB030036 == 1;
00042 00009 MB05586F = 1;
00043 00010 IOW MB076010 == 1;
00044 00011 IEND;
00045 " Break Table Blow Off
00046 00012 MB05587F = 1; " Break Table Blow Off Request
00047 00013 IOW MB05687F | MB000800 == 1 " Break Table Blow Off Chec
00048 00014 ELSE;
00049 00015 IF ML05310 == 1 " Last Chuck Break Use
00050 00016 IF MB30036 == 1;
00051 " Break Table Vaccum On
00052 00017 IF MB05685F == 1 " SCT Break Table Vacuum All Off
00053 " Break Table Vaccum On
00054 00018 MB05584F = 1; " Break Table Vacuum On Request
00055 00019 IOW MB05684F | MB000800 == 1 " Break Table Vacuum On Check
00056 00020 TIM TMW26202; " Break Table Vacuum On Delay Time
00057 00021 IEND;
00058 00022 IEND;
00059 00023 IEND;
00060 00024 IEND;
00061
00062 00025 IEND;
00063
00064 " Brush Interference Noting Check
00065 " Table Cleaning Brush Up Statu
00066 00026 IF !MB05682E | !MB05682F == 1;
00067 " Table Cleaning Brush Up Statu
00068 00027 MB05582E = 1; " Break Table Brush1 Up
00069 00028 MB05582F = 1; " Break Table Brush2 Up
00070 00029 IOW MB05682E & MB05682F == 1;
00071 00030 IEND;
00072
00073 " Scribe Unit Home Complete Waiting
00074 00031 IOW MB045240 == 1;
00075
00076 00032 PFORK Line1 Line2;
00077
00078 Line1:
00079
00080 00033 IF !MB04524A == 1;
00081 " P Work : Break Table
00082 00034 IF MB30036 == 1;
00083 00035 IF !MB56006 | !MB56026 | !MB56050 == 1;
00084 " Break Table Y, Z, T Carry Out Position
00085 00036 MSEE MPS304;
00086 00037 IEND;

```

```
00087 00038      ELSE;
00088 00039          IF !MB56000 | !MB56020 | !MB56050 == 1;
00089              " Break Table Y, Z, T Wait Position
00090 00040              MSEE MPS305;
00091 00041          IEND;
00092 00042      IEND;
00093 00043  ELSE;
00094      " Break Table Step Continue Request
00095 00044      EOX;
00096 00045      DB00060 = 0;
00097 00046      DL00060 = ILB296 - ILB316;
00098 00047      IF DL00060 < -2000;
00099 00048          DB00060 = 1;
00100 00049      ELSE;
00101 00050          IF DL00060 > 2000;
00102 00051              DB00060 = 1;
00103 00052          IEND;
00104 00053      IEND;
00105 00054      IF DB00060 == 1;
00106 00055          DL00062 = ILB28E - ILB296;
00107 00056          IF DL00062 > -5000;
00108 00057              IF DL00062 < 5000;
00109 00058                  DB00061 = 1;
00110 00059              IEND;
00111 00060          IEND;
00112 00061      IEND;
00113 00062      IF DB00060 & DB00061 == 1;
00114 00063          ML16138 = ILB28E;
00115 00064          MOV [BKTY1]ML16138 [BKTY2]ML16138;
00116 00065          IEND;
00117 00066      IEND;
00118
00119 00067      JOINTO Label1X;
00120
00121      Line2:
00122 00068          JOINTO Label1X;
00123 00069      Label1X: PJOINT
00124
00125      " Break Table Unit Ready
00126 00070      MB05571F = 1;
00127
00128 00071      MB055006 = 1;
00129 00072      MB055011 = 1;
00130
00131 00073      END;
```

" Break Table Y Pos. Moving

" Home Complete

" Auto Ready Complete