

```
00001      " Name:Step Control
00002      " Func:Step Control
00003      " From:MPM011
00004
00005  VAR;
00006 00000      LONG L1_PW = 0, " Line1 Axis Word Offset
00007 00001      LONG L1_PL = 0, " Line1 Axis Word Offset
00008  END_VAR;
00009
00010 00002      L1_PW = (MW02782-1) * 100      " Parameter Index
00011 00003      L1_PL = (MW02782-1) * 100 / 2  " Parameter Index
00012
00013 00004      ML02624 = ML02786      " Step travel distanc
00014
00015 00005      MB026002 = MB027841      " Moving direction(JOG/STEP)
00016
00017 00006      IF MB027840 == 1;
00018      " High Speed
00019 00007      ML02612 = ML40000[L1_PL]      " Speed reference setting
00020 00008      ELSE;
00021      " Low Speed
00022 00009      ML02612 = ML40002[L1_PL]      " Speed reference setting
00023 00010      IEND;
00024
00025 00011      MW02610 = 8;      " Motion command <- STEP COMMAND
00026 00012      IOW MB02700B == 1      " Motion command response code not 0
00027 00013      IOW MB027008 == 1      " Motion command execution completed
00028 00014      MW02610 = 0;      " Motion command <- 0 Clear
00029 00015      IOW MB027009 == 1      " Motion command response code is 0
00030
00031 00016  RET;
```