

```

00001      " Name:ServoParamSetting
00002      " Func:Set the servo axis parameter like this.
00003      "      Change Acceleration Time
00004      "      Change Deceleration Time
00005      "      Change Filter Time Constant
00006      "      Change Filter Type
00007      "      Error count alarm detection
00008      "      SoftLimit+
00009      "      SoftLimit-
00010      " From:MPM012
00011
00012  VAR;
00013 00000      LONG L1_SW = 0, " Line1 Servo Word Registor
00014 00001      LONG L2_SW = 0, " Line2 Servo Word Registor
00015 00002      LONG L3_SW = 0, " Line3 Servo Word Registor
00016 00003      LONG L4_SW = 0, " Line4 Servo Word Registor
00017 00004      LONG L5_SW = 0, " Line5 Servo Word Registor
00018 00005      LONG L6_SW = 0, " Line6 Servo Word Registor
00019 00006      LONG L7_SW = 0, " Line7 Servo Word Registor
00020
00021 00007      LONG L1_SL = 0, " Line1 Servo Long Registor
00022 00008      LONG L2_SL = 0, " Line2 Servo Long Registor
00023 00009      LONG L3_SL = 0, " Line3 Servo Long Registor
00024 00010      LONG L4_SL = 0, " Line4 Servo Long Registor
00025 00011      LONG L5_SL = 0, " Line5 Servo Long Registor
00026 00012      LONG L6_SL = 0, " Line6 Servo Long Registor
00027 00013      LONG L7_SL = 0, " Line7 Servo Long Registor
00028
00029 00014      LONG L1_SB = 0, " Line1 Servo Bit Registor
00030 00015      LONG L2_SB = 0, " Line2 Servo Bit Registor
00031 00016      LONG L3_SB = 0, " Line3 Servo Bit Registor
00032 00017      LONG L4_SB = 0, " Line4 Servo Bit Registor
00033 00018      LONG L5_SB = 0, " Line5 Servo Bit Registor
00034 00019      LONG L6_SB = 0, " Line6 Servo Bit Registor
00035 00020      LONG L7_SB = 0, " Line7 Servo Bit Registor
00036
00037 00021      LONG L1_PW = 0, " Line1 Axis Parameter Word Offset
00038 00022      LONG L2_PW = 0, " Line2 Axis Parameter Word Offset
00039 00023      LONG L3_PW = 0, " Line3 Axis Parameter Word Offset
00040 00024      LONG L4_PW = 0, " Line4 Axis Parameter Word Offset
00041 00025      LONG L5_PW = 0, " Line5 Axis Parameter Word Offset
00042 00026      LONG L6_PW = 0, " Line6 Axis Parameter Word Offset
00043 00027      LONG L7_PW = 0, " Line7 Axis Parameter Word Offset
00044
00045 00028      LONG L1_PL = 0, " Line1 Axis Parameter Long Offset
00046 00029      LONG L2_PL = 0, " Line2 Axis Parameter Long Offset
00047 00030      LONG L3_PL = 0, " Line3 Axis Parameter Long Offset
00048 00031      LONG L4_PL = 0, " Line4 Axis Parameter Long Offset
00049 00032      LONG L5_PL = 0, " Line5 Axis Parameter Long Offset
00050 00033      LONG L6_PL = 0, " Line6 Axis Parameter Long Offset
00051 00034      LONG L7_PL = 0, " Line7 Axis Parameter Long Offset
00052
00053 00035      LONG L1_ML = 0, " Line1 Axis Internal Data(2word)
00054 00036      LONG L2_ML = 0, " Line2 Axis Internal Data(2word)
00055 00037      LONG L3_ML = 0, " Line3 Axis Internal Data(2word)
00056 00038      LONG L4_ML = 0, " Line4 Axis Internal Data(2word)
00057 00039      LONG L5_ML = 0, " Line5 Axis Internal Data(2word)
00058 00040      LONG L6_ML = 0, " Line6 Axis Internal Data(2word)
00059 00041      LONG L7_ML = 0, " Line7 Axis Internal Data(2word)
00060  END_VAR;
00061
00062 00042      PFORK Line1 Line2 Line3 Line4 Line5 Line6 Line7 Line8;
00063      Line1:
00064 00043          JOINTO LabelX;
00065      Line2:
00066 00044          JOINTO LabelX;
00067      Line3:
00068 00045          JOINTO LabelX;
00069      Line4:
00070 00046          JOINTO LabelX;
00071      Line5:
00072 00047          JOINTO LabelX;
00073      Line6:
00074 00048          JOINTO LabelX;
00075      Line7:
00076 00049          JOINTO LabelX;
00077      Line8:
00078 00050          JOINTO LabelX;
00079 00051      LabelX: PJOINT;
00080
00081 00052      RET;
00082

```