

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : [Step.03] Alignment Exec 1 Cycle
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 00000 IF ML05308 == 1;
00021 " Dummy Pusher Bar
00022 00001 MW04844 = 1; " Break Code Write ( 1 : Pusher Bar , 2
: Last , 3 : Break Table )
00023 00002 IEND;
00024
00025 00003 IF ML05310 == 1;
00026 " Last Dummy Pusher Bar
00027 00004 MW04844 = 2; " Break Code Write ( 1 : Pusher Bar , 2
: Last , 3 : Break Table )
00028 00005 IEND;
00029 00006 IF ML05810 == 1;
00030 " Table Break
00031 00007 MW04844 = 3; " Break Code Write ( 1 : Pusher Bar , 2
: Last , 3 : Break Table )
00032 00008 IEND;
00033
00034 " Receive Position Moving Complete
00035 00009 IF MB045130 == 1;
00036 00010 MW04844 = 100;
00037 00011 IEND;
00038
00039 " Manual PTP
00040 00012 IF !MB000004 == 1;
00041 00013 IF ML04858 <> 1;
00042 00014 MSEE MPS257; " Chuck,Table Break Escape Position 1 Cy
cle
00043 " It's not recipe dat
00044 00015 IF !MB000004 & !MB225580 == 1;
00045 00016 MW04844 = 100;
00046 00017 IEND;
00047 00018 IEND;
00048 00019 IEND;
00049
00050 00020 MB4572F = 0; " Break Alignment Position Comp Bit
00051
00052 00021 PFORK ALIGN BRK BLOW
00053 " Alignment Position Move & Execute
00054 ALIGN:
00055 00022 IF MW04844 > 1;
00056 00023 IF CW00099 == 1;
00057 00024 IF MW04844 == 3;
00058 00025 DL00030 = ML73806 + CW00218;
00059 00026 IOW DL00030 > ILB296;
00060 // IOW MB4572F | MB045013 == 1;
00061 00027 ELSE;
00062 00028 IOW MB4572F | MB045013 == 1;
00063 00029 IEND;
00064 00030 ELSE;
00065 00031 IOW MB4572F | MB045013 == 1;
00066 00032 IEND;
00067 00033 IEND;
00068 " Alignment Execute 1 Cycle
00069 00034 IF MB045013 == 0 " Cycle Stop(SC)
00070 00035 MSEE MPS195; " Alignment Execute 1 Cycle
00071 00036 IEND;
00072
00073 00037 JOINTO LabelX;
00074
00075 " Pusher Bar Receive Before Position Mo
00076 BRK:
00077 " Receive Position Type
00078 00038 SFORK MW04844 == 1 ? LBL20 " Pusher Bar Mode
00079 MW04844 == 2 ? LBL21 " Last Dummy Pusher Bar Mode
00080 MW04844 == 3 ? LBL22 " Table Break Mode
00081 DEFAULT ? LBL101;
00082
00083 00039 LBL20:

```

```

00084      " Pusher Bar is Not Comman
00085 00040      DW00010 = 0;
00086 00041      WHILE DB000100 | MB045013 == (
00087 00042          IF MW04520 == 0
00088 00043              DB000101 = 1;
00089 00044          IEND;
00090 00045          IF MW05008 == 0
00091 00046              DB000102 = 1;
00092 00047          IEND;
00093 00048          IF MB04572A == 0
00094 00049              DB000103 = 1;
00095 00050          IEND;
00096 00051          IF MB030036 == 0
00097 00052              DB000104 = 1;
00098 00053          IEND;
00099
00100 00054          IF DB000101 & DB000102 & DB000103 "& DB000104" == 1;
00101 00055              DB000100 = 1;
00102 00056          IEND;
00103 00057          EOX;
00104 00058      WEND;
00105
00106 00059      IF MB045013 == 0
00107          " [ SC ↔ BKPБ ] Motion InterFace
00108          MW04520 = 1;
00109 00061          MB045210 = 1;
00110
00111 00062          IOW MB045211 == 1
00112 00063          MB045210 = 0;

00113 00064          IOW MB045211 == 0
00114 00065          MW04520 = 0;

00115
00116 00066          IOW MB04572A == 0
00117
00118 00067          MW04520 = 0;
00119 00068          MB045210 = 0;

00120 00069          EOX;
00121
00122          " [ SC ↔ BKPБ ] Motion InterFace
00123 00070          MW04520 = 2;
00124 00071          MB045210 = 1;
00125
00126 00072          IOW MB045211 == 1
00127 00073          MB045210 = 0;

00128 00074          IOW MB045211 == 0
00129 00075          MW04520 = 0;

00130
00131 00076          IOW MB04572A == 0
00132
00133 00077          MW04520 = 0;
00134 00078          MB045210 = 0;
00135
00136 00079          MB4572F = 1;
00137 00080      IEND;
00138
00139 00081      JOINTO LBL1X;
00140
00141 00082      LBL21:
00142          " Break Table is Not Command
00143          DW00011 = 0;
00144 00084          WHILE DB000110 | MB045013 == 0;
00145 00085              IF MW04522 == 0
00146 00086                  DB000111 = 1;
00147 00087              IEND;
00148 00088              IF MW05508 == 0
00149 00089                  DB000112 = 1;
00150 00090              IEND;
00151 00091              IF (MB076010 | MB07601A | MB076002 | MB076003) & MB055696 == " Tranfer Z Home Pos
ition Check
00152 00092                  DB000113 = 1;
00153 00093              IEND;
00154 00094              IF DB000111 & DB000112 & DB000113 == 1;
00155 00095                  DB000110 = 1;
00156 00096              IEND;
00157 00097              EOX;
00158 00098          WEND;
00159
00160          " Not Glass
00161 00099          IF ML05310 == 0;
00162 00100              IOW !MB030036 | MB045013 == 1;
00163 00101          ELSE;
00164 00102              IF MB030035 == 1;
00165 00103                  IOW !MB030036 | MB045013 == 1;
00166 00104              IEND;

```

```

00167 00105      IEND;
00168
00169      //      IF CW00061 <> 1;
00170      //      " Scribe Cutter X Alignment Position Movi
00171      //      IOW MW04514 == 0
00172      //      MW04514 = 2;      " Scribe → Scribe Cutter Command Code S
      etting
00173      //      MB045150 = 1;      " Scribe → Scribe Cutter Command Execut
      e Bit On
      //
00174      IEND;
00175
00176 00106      IF (!MB056002 & !MB056022) == 1;
00177 00107      IF MB04524A == 1;
00178      " [ SC ↔ TBL ] Motion InterFace
00179 00108      MW04522 = 2;      " [ SC Req TBL ] Command Code ID Set
00180 00109      MB045230 = 1;      " [ SC Req TBL ] Command Se
00181 00110      IOW MB045231 == 1      " [ SC ← TBL ] Command Complete
00182 00111      MB045230 = 0;      " [ SC Req TBL ] Command Se

00183 00112      IOW MB045231 == 0      " [ SC ← TBL ] Command Complete
00184 00113      MW04522 = 0;      " [ SC Req TBL ] Command Code ID Set
00185 00114      IEND;
00186 00115      IEND;
00187
00188 00116      IF !MB04524A == 1;
00189      " [ SC ↔ TBL ] Motion InterFace
00190 00117      MW04522 = 1;      " [ SC Req TBL ] Command Code ID Set
00191 00118      MB045230 = 1;      " [ SC Req TBL ] Command Se
00192 00119      IOW MB045231 == 1      " [ SC ← TBL ] Command Complete
00193 00120      MB045230 = 0;      " [ SC Req TBL ] Command Se

00194 00121      IOW MB045231 == 0      " [ SC ← TBL ] Command Complete
00195 00122      MW04522 = 0;      " [ SC Req TBL ] Command Code ID Set
00196
00197 00123      MB04572F = 1;
00198 00124      ELSE;
00199 00125      MB04572F = 1;
00200 00126      IEND;
00201
00202      //      IF CW00061 <> 1;
00203      //      " Scribe Cutter X Alignment Position Moving Check
00204      //      IOW MB045151 == 1      " Scribe ← Scribe Cutter Command Co
      mplete Bit On
00205      //      MB045150 = 0;      " Scribe → Scribe Cutter Command Ex
      ecute Bit Off
00206      //      IOW MB045151 == 0      " Scribe ← Scribe Cutter Command Co
      mplete Bit On
      //
00207      IEND;
00208
00209 00127      JOINTO LBL1X;
00210
00211 00128      LBL22:
00212      " Table Break is Not Command
00213 00129      DW00012 = 0;
00214 00130      WHILE DB000120 | MB045013 == 0;
00215 00131      IF MW04522 == 0      " [ SC Req TBL ] Command Code ID Set
00216 00132      DB000121 = 1;
00217 00133      IEND;
00218 00134      IF MW05508 == 0      " [ SC Req TBL ] Command Code ID Copy
00219 00135      DB000122 = 1;
00220 00136      IEND;
00221 00137      IF (MB076010 | MB07601A | MB076002 | MB076003) & MB055696 ==      " Transf
      er Z Home Position Check
      DB000123 = 1;
00222 00138      IEND;
00223 00139      IF DB000121 & DB000122 & DB000123 == 1;
00224 00140      DB000120 = 1;
00225 00141      IEND;
00226 00142      EOX;
00227 00143
00228 00144      WEND;
00229
00230      " Not Glass
00231 00145      IF ML05310 == 0;
00232 00146      IOW !MB030036 | MB045013 == 1;
00233 00147      ELSE;
00234 00148      IF MB030035 == 1;
00235 00149      IOW !MB030036 | MB045013 == 1;
00236 00150      IEND;
00237 00151      IEND;
00238
00239 00152      IF ML26280 <> 0      " Align, Table Break Head Move Same Time
      (0:Unuse/1:Odd Use/2:Even Use/3:All Use)
      DW00020 = MW12513;
00240 00153      DW00021 = MOD;
00241 00154      IF ML26280 == 1;
00242 00155      IF DW00021 == 1;
00243 00156      " Scribe Cutter X Alignment Position Movi
00244

```

```

00245 00157          IOW MW04514 == 0
00246 00158          MW04514 = 2;          " Scribe → Scribe Cutter Command Code S
etting
00247 00159          MB045150 = 1;          " Scribe → Scribe Cutter Command Execut
e Bit On
00248 00160          IEND;
00249 00161          IEND;
00250 00162          IF ML26280 == 2;
00251 00163          IF DW00021 == 0;
00252          " Scribe Cutter X Alignment Position Movi
00253 00164          IOW MW04514 == 0
00254 00165          MW04514 = 2;          " Scribe → Scribe Cutter Command Code S
etting
00255 00166          MB045150 = 1;          " Scribe → Scribe Cutter Command Execut
e Bit On
00256 00167          IEND;
00257 00168          IEND;
00258 00169          IF ML26280 == 3;
00259          " Scribe Cutter X Alignment Position Movi
00260 00170          IOW MW04514 == 0
00261 00171          MW04514 = 2;          " Scribe → Scribe Cutter Command Code S
etting
00262 00172          MB045150 = 1;          " Scribe → Scribe Cutter Command Execut
e Bit On
00263 00173          IEND;
00264 00174          IEND;
00265
00266 00175          IF MB045013 == 0          " Cycle Stop(SC)
00267 00176          IF !MB04524A == 1;
00268          " [ SC ↔ TBL ] Motion InterFace
00269 00177          MW04522 = 1;          " [ SC Req TBL ] Command Code ID Set
00270 00178          MB045230 = 1;          " [ SC Req TBL ] Command Se
00271 00179          IOW MB045231 == 1          " [ SC ← TBL ] Command Complete
00272 00180          MB045230 = 0;          " [ SC Req TBL ] Command Se

00273 00181          IOW MB045231 == 0          " [ SC ← TBL ] Command Complete
00274 00182          MW04522 = 0;          " [ SC Req TBL ] Command Code ID Set
00275
00276 00183          MB04572F = 1;
00277 00184          ELSE;
00278 00185          MB04572F = 1;
00279 00186          IEND;
00280 00187          IEND;
00281
00282 00188          IF ML26280 == 0          " Align, Table Break Head Move Same Time
(0:Unuse/1:Odd Use/2:Even Use/3:All Use)
00283 00189          IOW MB046083 == 1          " SCHY Alignment Position
00284
00285 00190          IOW MW04514 == 0
00286 00191          MW04514 = 2;          " Scribe → Scribe Cutter Command Code S
etting
00287 00192          MB045150 = 1;          " Scribe → Scribe Cutter Command Execut
e Bit On
00288 00193          IEND;
00289
00290          " Scribe Cutter X Alignment Position Moving Check
00291 00194          IOW MB045151 == 1          " Scribe ← Scribe Cutter Command Comple
te Bit On
00292 00195          MB045150 = 0;          " Scribe → Scribe Cutter Command Execut
e Bit Off
00293 00196          IOW MB045151 == 0          " Scribe ← Scribe Cutter Command Comple
te Bit Or
00294
00295 00197          JOINTO LBL1X;
00296
00297 00198          LBL101:          " Default Step
00298
00299          MB04572F = 1;
00300
00301 00200          JOINTO LBL1X;
00302 00201          LBL1X: SJOINT;
00303 00202          JOINTO LabelX;
00304
00305          BLOW:
00306 00203          IF MB000004 == 1          " Automatic Drivin
00307          " Break Table Glass Data Not Exis
00308 00204          IF MB030036 == 0;
00309 00205          IF MB053080 == 1;
00310          " Break Table Glass Data Exis
00311          " Cutting Table Blow On
00312 00206          MB09057F = 1;          " Cutting Table Blow On Reques

00313
00314          " [Action] Cutting Table Vacuum Off
00315 00207          IF !MB09023F == 1;
00316          " Cutting Table Vacuum Off
00317 00208          MB09053F = 1;          " Cutting Table Vacuum Off Request

```

```
00318 00209          IEND;
00319 00210      ELSE;
00320          " Cutting Table Blow On
00321 00211      MB09057F = 1;          " Cutting Table Blow On Request
00322          " Break Table Blow On
00323 00212      MB05586F = 1;          " Break Table Blow On Request
00324
00325          " [Action] Cutting Table Vacuum Off
00326 00213      IF !MB09023F == 1;
00327          " Cutting Table Vacuum Off
00328 00214      MB09053F = 1;          " Cutting Table Vacuum Off Request
00329 00215      IEND;
00330          " [Action] Break Table Vacuum Off
00331 00216      IF !MB05685F == 1          " Break Table Vacuum Off Status
00332          " Break Table Vacuum Off
00333 00217      MB05585F = 1;          " Break Table Vacuum Off Request
00334 00218      IEND;
00335 00219      IEND;
00336 00220      ELSE;
00337          " Break Table Glass Data Exist
00338 00221      IF GL21158 > MW15411;
00339          " Cutting Table Blow On
00340 00222      MB09057F = 1;          " Cutting Table Blow On Request

00341          " [Action] Cutting Table Vacuum Off
00342 00223      IF !MB09023F == 1;
00343          " Cutting Table Vacuum Off
00344 00224      MB09053F = 1;          " Cutting Table Vacuum Off Request
00345 00225      IEND;
00346 00226      IEND;
00347 00227      IEND;
00348 00228      IEND;
00349
00350 00229      JOINTO LabelX;
00351 00230      LabelX: PJOINT;
00352
00353 00231      IF MB000004 == 1;
00354
00355 00232      ELSE;
00356 00233          IF MW00051 == 82          " [Position] Alignment Position
00357 00234          IF MW04844 == 2          " Break Code Write ( 1 : Pusher Bar , 2
: Last , 3 : Break Table )
          MW04511 = 3;
00358 00235          IEND;
00359 00236          IEND;
00360 00237          IF MW00051 == 97          " [1Cycle] Alignment Execute 1 Cycle
00361 00238          IF MW04844 == 2          " Break Code Write ( 1 : Pusher Bar , 2
00362 00239          : Last , 3 : Break Table )
          MW04511 = 3;
00363 00240          IEND;
00364 00241          IEND;
00365 00242          IEND;
00366 00243          IEND;
00367
00368          " Interlock _ Receive 1 Cycle Complete Check
00369 00244      IOW MB04572F | MB045013 == 1;
00370
00371 00245      RET;
```