

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : [Step.10] Break Pusher Bar 1 Cycle
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017
00018 END_VAR;
00019
00020 00000 PFORK BCHK CUTX SCHY;
00021
00022 " Break Pusher Bar 1 Cycle & Cutter X Waiting Position
00023 BCHK:
00024 " Break Pusher Bar is Not Commar
00025 DW00010 = 0;
00026 WHILE DB000100 == 0;
00027 00003 IF MW04520 == 0 " [ SC Req BCHK ] Command Code ID Set
00028 00004 DB000101 = 1;
00029 00005 IEND;
00030 00006 IF MW05008 == 0 " [ SC Req BCHK ] Command Code ID Copy
00031 00007 DB000102 = 1;
00032 00008 IEND;
00033 00009 IF MB04572A == 0 " BCHK Moving Flag Off Check
00034 00010 DB000103 = 1;
00035 00011 IEND;
00036 00012 IF MB046030 | MB046036 | MB04515B == " [ All ] Cutter Shift Escape Po
sition
00037 00013 DB000104 = 1;
00038 00014 IEND;
00039 00015 IF MB045741 == 1 " [ All ] Cutter Shift Escape Position
00040 00016 DB000105 = 1;
00041 00017 IEND;
00042 00018 IF (DB000101 & DB000102 & DB000103 & DB000104 & DB000105) == 1;
00043 00019 DB000100 = 1;
00044 00020 IEND;
00045
00046 00021 EOX;
00047 00022 WEND;
00048
00049 " Break Pusher Bar Position Check
00050 00023 DB000010 = 0;
00051 00024 IF !MB050742 & !MB045135 == 1;
00052 00025 DB000010 = 1;
00053 00026 IEND;
00054
00055 " Break Pusher Bar Home Origin 1 Cycle
00056 00027 IF MB000004 & DB000010 == 1;
00057 " Transfer Z Home Position Check
00058 // IOW MB071020 == 1;
00059 00028 IF ILB296 < ML73802;
00060 " [Step.05] Table Break Waitting Pos 1 Cycle
00061 " [ SC Int TBL ] Motion InterFace
00062 00029 IOW MW05508 == 0 " TBL Command Code ID Check
00063 00030 IOW MW04522 == 0 " [ SC Req TBL ] Command Code ID Che
ck
00064 00031 MW04522 = 7; " [ SC Req TBL ] Command Code ID Set
00065 00032 MB045230 = 1; " [ SC Req TBL ] Command Se
00066 00033 IOW MB045231 == 1 " [ SC Res TBL ] Command Complete
00067 00034 MB045230 = 0; " [ SC Req TBL ] Command Se
00068 00035 IOW MB045231 == 0 " [ SC Res TBL ] Command Complete
00069 00036 MW04522 = 0; " [ SC Req TBL ] Command Code ID Set
00070 00037 IEND;
00071 " Break Table No Cammand Chec
00072 // IOW ILB296 >= ML73802;
00073 // IOW MB055696 & MB056000"MB056005" == ;
00074
00075 00038 IF MB051000 & MB051020 == 0;
00076 " [Step.10] Break Pusher Bar Waiting Position
00077 " [ SC Int BCHK ] Motion InterFace
00078 00039 MW04520 = 10; " [ SC Req BCHK ] Command Code ID Set
00079 00040 MB045210 = 1; " [ SC Req BCHK ] Command Se
00080 00041 IOW MB045211 == 1 " [ SC Res BCHK ] Command Complete
00081 00042 MB045210 = 0; " [ SC Req BCHK ] Command Se
00082 00043 IOW MB045211 == 0 " [ SC Res BCHK ] Command Complete
00083 00044 MW04520 = 0; " [ SC Req BCHK ] Command Code ID S

```

```

00084
00085 00045          IOW MB04572A == 0          " BCHK Moving Flag OFF
00086
00087 00046          IOW MB051000 & MB051020 == 1      " Break Pusher Bar Waiting Position
00088 00047      IEND;
00089
00090 00048      IF MB045134 == 1;
00091          " [Step.03] Break Pusher Bar Start
00092          " [ SC Int BCHK ] Motion InterFace
00093 00049          IOW MB046084 == 1          " Scribe Chuck Y Break Position Check
00094 00050          IOW MW04518 == 0          " [ SC Req SCHK ] Command Code ID Set
00095
00096 00051          MW04520 = 3;          " [ SC Req BCHK ] Command Code ID Set
00097 00052          MB045210 = 1;          " [ SC Req BCHK ] Command Set
00098 00053          IOW MB045211 == 1      " [ SC Res BCHK ] Command Complete
00099 00054          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00100 00055          IOW MB045211 == 0      " [ SC Res BCHK ] Command Complete
00101 00056          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID S

00102
00103 00057          IOW MB04572A == 0          " BCHK Moving Flag OFF
00104
00105 00058          IOW MB050743 == 1      " Break Pusher Bar Start Positi

00106 00059      IEND;
00107 00060      IEND;
00108
00109 00061      IF MB045134 == 0          " Break Pusher Bar Start Position 1 Cycl
e Complete Check
00110          " [Step.03] Break Pusher Bar Sta:
00111          " [ SC Int BCHK ] Motion InterFace
00112
00113 00062          IOW MB046084 == 1          " Scribe Chuck Y Break Position Check
00114 00063          IOW MW04518 == 0          " [ SC Req SCHK ] Command Code ID S

00115
00116 00064          MW04520 = 3;          " [ SC Req BCHK ] Command Code ID Set
00117 00065          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00118 00066          IOW MB045211 == 1      " [ SC Res BCHK ] Command Complete
00119 00067          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00120 00068          IOW MB045211 == 0      " [ SC Res BCHK ] Command Complete
00121 00069          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID S

00122
00123 00070          IOW MB04572A == 0          " BCHK Moving Flag OFF
00124
00125 00071          IF MB000004 == 1
00126 00072          MB045134 = 1;          " Break Pusher Bar Start Position 1 Cycl
e Complete Set
00127 00073      IEND;
00128 00074      IEND;
00129
00130 00075      IF MB045135 == 0          " Break Pusher Bar Execute 1 Cycle Compl
ete Check
00131          " [ SC Int BCHK ] Motion InterFace
00132 00076          MW04520 = 4;          " [ SC Req BCHK ] Command Code ID Set
00133 00077          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00134 00078          IOW MB045211 == 1      " [ SC Res BCHK ] Command Complete
00135 00079          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00136 00080          IOW MB045211 == 0      " [ SC Res BCHK ] Command Complete
00137 00081          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID Set
00138
00139 00082          IF MB000004 == 1
00140 00083          MB045135 = 1;          " Break Pusher Bar Execute 1 Cycle Compl
ete Set
00141 00084      IEND;
00142 00085      IEND;
00143
00144 00086      IF MB045136 == 0          " Break Pusher Bar Standby Pos 1 cycle C
omplete
00145
00146          " [ SC Int BCHK ] Motion InterFace
00147 00087          MW04520 = 10;          " [ SC Req BCHK ] Command Code ID Set
00148 00088          MB045210 = 1;          " [ SC Req BCHK ] Command Se
00149 00089          IOW MB045211 == 1      " [ SC Res BCHK ] Command Complete
00150 00090          MB045210 = 0;          " [ SC Req BCHK ] Command Se

00151 00091          IOW MB045211 == 0      " [ SC Res BCHK ] Command Complete
00152 00092          MW04520 = 0;          " [ SC Req BCHK ] Command Code ID Set
00153
00154 00093          MB045136 = 1;          " Break Pusher Bar Standby Pos 1 cycle C
omplete
00155

```

```

00156 00094      IEND;
00157
00158 00095      JOINTO LabelX;
00159
00160      CUTX:
00161
00162      " Cutter X Cutting After Escape Position
00163 00096      IF !MB045741 == 1;
00164 00097          MW04514 = 11;
00165 00098          MB045150 = 1;          " Scribe Req Scribe Cutter Command Execute B
it ON
00166 00099          IOW MB045151 == 1          " Scribe Res Scribe Cutter Command Complete
Bit ON
00167 00100          MB045150 = 0;          " Scribe Req Scribe Cutter Command Execute B
it OFF
00168 00101          IOW MB045151 == 0          " Scribe Res Scribe Cutter Command Complete
Bit ON
00169 00102      IEND;
00170
00171 00103      JOINTO LabelX;
00172
00173      SCHY:
00174
00175      " Scribe Y Break Position
00176 00104      IF !MB04608 == 1          " Scribe Chuck Y Break Position Check
00177 00105          IOW MW04518 == 0;
00178 00106          MW04518 = 14;          " Scribe → Scribe Chuck Command Code Settin
g
00179 00107          MB045190 = 1;          " Scribe → Scribe Chuck Command Execute Bit
On
00180 00108          IOW MB045191 == 1          " Scribe ← Scribe Chuck Command Complete Bi
t On
00181 00109          MB045190 = 0;          " Scribe → Scribe Chuck Command Execute Bit
Reset
00182 00110          IOW MB045191 == 0          " Scribe ← Scribe Chuck Command Complete Bi
t Resedt
00183
00184 00111          IOW MB046084 == 1          " Scribe Chuck Y Break Position Check
00185 00112      IEND;
00186
00187 00113      JOINTO LabelX;
00188 00114      LabelX: PJOINT;
00189
00190 00115      RET;

```